Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 0710 CALIBRATION DATE: 26-Feb-19

SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.79495256e-003 h = 6.76957307e-004 i = 2.92657049e-005 j = 2.65845678e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	5797.511	-1.5000	0.00001
1.0000	6132.342	1.0000	0.00004
4.5000	6624.244	4.5000	-0.00005
8.0000	7143.836	7.9999	-0.00011
11.5000	7691.861	11.5000	-0.00000
15.0000	8268.983	15.0001	0.00006
18.5000	8875.881	18.5001	0.00013
22.0000	9513.182	22.0001	0.00013
25.5000	10181.461	25.4999	-0.00014
29.0000	10881.376	28.9997	-0.00028
32.5000	11613.589	32.5002	0.00020

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

