Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

## Temperature Calibration Report

Pacific Marine Environmental Lab

Customer:	Pacific Marine Environmental Lab			
Job Number:	62473	Date of Re	port:	1/27/2011
Model Number	SBE 03Plus	Serial Nun	nber:	03P2786
Temperature sensors are normally calibrated 'as received', without adjustments, allowing a determination sensor drift. If the calibration identifies a problem, then a second calibration is performed after work is completed. The 'as received' calibration is not performed if the sensor is damaged or non-functional, or by customer request.				
must choose wheth during deployment allows a small corr	er the 'as received' calibrati . In SEASOFT enter the cl ection for drift between cali- pair apply only to subsequen		ter represents um SEACON.	the sensor condition The coefficient 'offset'
Date:	7	Drift since last cal:	Cironica	Degrees Celsius/year
Comments:	_			
'CALIBRATION			erformed	Not Performed
Date: 1/27/2011	J	Drift since Last cal:	-0.000	Degrees Celsius/year
Comments: The three pin con	nector was replaced.			