Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 6902 CALIBRATION DATE: 20-Dec-17 SBE 16plus V2 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

a0 = 1.244523e-003 a1 = 2.733836e-004 a2 = -7.615225e-007 a3 = 1.656730e-007

BATH TEMP (° C)	INSTRUMENT OUTPUT (counts)	INST TEMP (° C)	RESIDUAL (° C)
1.0000	564133.300	1.0000	0.0000
4.5000	498528.500	4.4999	-0.0001
15.0000	337971.100	15.0000	0.0000
18.5000	295400.700	18.5000	-0.0000
24.0000	237961.100	24.0000	-0.0000
29.0000	194506.600	28.9999	-0.0001
32.5000	168367.700	32.5000	0.0000

n = Instrument Output (counts)

MV = (n - 524288) / 1.6e + 007

R = (MV \* 2.900e + 0.09 + 1.024e + 0.08) / (2.048e + 0.04 - MV \* 2.0e + 0.05)

Temperature ITS-90 (°C) =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

