Customer:

Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Job Number:	86981	Date of	Report:		11/18/2015
Model Number	SBE 16Plus	Serial N	umber:	1	6P68701-6902
the calibration iden	tifies a problem, then	ated 'as received', without adjustme a second calibration is performed o is damaged or non-functional, or b	fter work	is completed	
must choose whethe during deployment.	er the 'as received' call In SEASOFT enter t	provided, listing coefficients to convibration or the previous calibration he chosen coefficients. The coefficients and coefficients are manual.	better rep ient 'offse	resents the t' allows a	sensor condition small correction for
'AS RECEIVED C	CALIBRATION'	<u> </u>	Perfor	med	☐ Not Performed
F		Drift since last o		med 0.00083	□ Not Performed □ Degrees Celsius/year
-					
Date: 11/18/2015					
Date: 11/18/2015	5			0.00083	
Date: 11/18/2015 Comments:	5		al: +	0.00083	Degrees Celsius/year