## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0580 CALIBRATION DATE: 08-Dec-11

SBE 39 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 6.359766e - 005a1 = 2.612923e-004a2 = -1.740037e - 006a3 = 1.499305e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
-1.5001	830150.3	-1.5001	0.0000
0.9999	741406.4	0.9999	0.0000
4.4999	634653.8	4.4999	-0.0000
7.9999	545009.2	7.9999	-0.0000
11.4999	469481.0	11.4999	0.0000
14.9999	405641.0	14.9999	0.0000
18.4999	351511.4	18.4999	0.0000
21.9999	305473.0	21.9999	0.0000
25.4999	266202.2	25.4998	-0.0001
28.9999	232604.5	28.9999	-0.0000
32.4999	203780.0	32.4999	0.0000

Temperature ITS-90 =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

