

Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 5584 CALIBRATION DATE: 27-Jul-19 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.40701404e-003 h = 6.41853884e-004 i = 2.32809937e-005 j = 2.21183299e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3239.136	-1.5000	0.00003
1.0000	3426.995	1.0000	-0.00002
4.5000	3703.099	4.5000	-0.00003
8.0000	3994.882	8.0000	0.00001
11.5000	4302.761	11.5000	-0.00003
15.0000	4627.172	15.0001	0.00008
18.5000	4968.485	18.5000	-0.00001
22.0000	5327.113	22.0000	-0.00004
25.5000	5703.433	25.5000	-0.00001
29.0000	6097.796	29.0000	-0.00001
32.5000	6510.553	32.5000	0.00002

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

