Conductivity Calibration Report

Customer:	Pacific Marine Er	nvironmental Lab		
Job Number:	62473	Date of Re	port:	1/19/2011
Model Number	SBE 37SM	Serial Num	ıber:	37SM24246-1679
sensor drift. If the	calibration identifies a rk is completed. The 'a	ed 'as received', without cleaning or ac problem or indicates cell cleaning is n s received' calibration is not performed	ecessary, then	a second calibration is
An 'as received' calibration certificate is provided, listing the coefficients used to convert sensor frequency to conductivity. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients using the program SEACON. The coefficient 'slope' allows small corrections for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair or cleaning apply only to subsequent data.				
'AS RECEIVED (CALIBRATION'	✓ P	erformed	☐ Not Performed
Date: 1/19/2011		Drift since last cal:	0.0	PSU/month
Comments:				
'CALIBRATION	AFTER CLEANING	S & REPLATINIZING' D	erformed	✓ Not Performed
Date:		Drift since Last cal:		PSU/month
Comments:				
*Measured at 3.0	S/m			

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.