Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 0521 CALIBRATION DATE: 16-Jan-21

SBE 16 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

 $\begin{array}{lll} g &=& 4.24274335e-003 \\ h &=& 6.08479378e-004 \\ i &=& 5.83625805e-006 \\ j &=& -1.49016674e-006 \end{array}$

f0 = 1000.0

BATH TEMP (° C)	INSTRUMENT OUTPUT (Hz)	INST TEMP (° C)	RESIDUAL (° C)
1.0000	2690.661	0.9998	-0.00022
4.4999	2908.111	4.5003	0.00040
15.0000	3634.632	14.9997	-0.00031
18.5000	3902.778	18.5000	-0.00005
24.0000	4351.632	24.0000	0.00003
29.0000	4789.860	29.0004	0.00043
32.5001	5114.170	32.4998	-0.00029

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual (${}^{\circ}C$) = instrument temperature - bath temperature

