Comments:

Temperature Calibration Report

Customer:	Pacific Marine Environmental Lab			
Job Number:	62186	Date of Re	eport:	12/17/2010
Model Number	SBE 39	Serial Nun	nber:	3935165-1424
If the calibration is calibration is not possible. An 'as received' calibration calibration is not possible. An 'as received' calibration is not possible.	lentifies a problem, the erformed if the sensor libration certificate is per the 'as received' cale. In SEASOFT enter the tothe for drift between air apply only to subse	•	ter work is con ustomer reques sensor frequen tter represents am SEACON.	npleted. The 'as received' it. ncy to temperature. Users the sensor condition The coefficient 'offset'
Date: 12/17/2010	0	Drift since last cal:	+0.0000	Degrees Celsius/year
Comments:				
'CALIBRATION	AFTER REPAIR'	□ F	Performed	✓ Not Performed
Date:	7	Drift since Last cal:	:	Degrees Celsius/year