

1700/1725 Brannum Lane Yellow Springs OH 45387 USA tel: 937-767-7241 fax: 937-767-9320

YSI SonTek Aanderaa WaterLog / DAA MJK

Date: 7/16/2014

Estimate for Service Request #:

306378

Bill To:

Noaa

7600 Sand Point Way N.E.

Wc3

Scott Mckeever Seattle, Wa-98115 **Customer #:** 16270

Quoted by: Baxter, Jason

Please Contact me at

Phone #: 937-767-7241 option 4

Fax #:

Email: repairs@ysi.com

Email/Fax: scott.mckeever@noaa.gov, shawn.sneddon@xyleminc.com Contact: SCOTT MCKEEVER Phone#: 1-206-5266205

Repair #: 167407

Order #: 654015

Part #	Description	List Price	Qty	Charged Price
ROPTODE	REPAIR,OPTODE			
LABOR-OPTODE CALIBRATION	Labor-Optode Calibration Charge	\$700.00	1	\$700.00
1206005C	Oxygen Sensor Foils	\$171.67	1	\$171.67

Technician's Notes:	MODEL; 3835 OPTODE SN: 1033	Total for this Repair:	\$871.67
	REPORTED SYMPTOM: CALIBRATE AND SERVICE		
	TECHNICIAN NOTES: -VERIFIED CURRENT CONSUMPTION (SLEEP AND RUN), CURRENT IS IN SPEC.		
	-FIRMWARE UPDATED FROM 3.11 TO 3.24.		
	-FOIL HAS LARGE HOLE. REPLACED FOIL WITH PART# 1206005C, CALIBRATED SENSOR.		
	-POST-CALIBRATION DATA: SN1033 REPORTS 100.98% DO IN 100.76% BATH. TEMP REPORTS 10.11 IN 10.11 DEG C BATH.		
	FINAL TEST - MEETS AADI SPECS		

Repair #: 167408

Order #: 654015

Topan in the formation and the first terms of the f				
Part#	Description	List Price	Qty	Charged Price
ROPTODE	REPAIR,OPTODE			
LABOR-OPTODE CALIBRATION	Labor-Optode Calibration Charge	\$700.00	1	\$700.00
1206005C	Oxygen Sensor Foils	\$171.67	1	\$171.67

Technician's Notes:	MODEL; 3835 OPTODE SN: 1094	Total for this Repair:	\$871.67
	REPORTED SYMPTOM: CALIBRATE AND SERVICE		
	TECHNICIAN NOTES: -VERIFIED CURRENT CONSUMPTION (SLEEP AND RUN), CURRENT IS IN SPEC.		
	-FIRMWARE UPDATED FROM 3.11 TO 3.24.		
	-FOIL IS WORN, DULL IN APPEARANCE. REPLACED FOIL WITH PART# 1206005C, CALIBRATED SENSOR.		
	-POST-CALIBRATION DATA: SN1094 REPORTS 100.74% DO IN		

PLEASE FAX THIS QUOTE WITH WRITTEN AUTHORIZATION. PLEASE INCLUDE YOUR PO#. YSI CANNOT MAKE ANY REPAIRS WITHOUT WRITTEN AUTHORIZATION











1700/1725 Brannum Lane Yellow Springs OH 45387 USA tel: 937-767-7241 fax: 937-767-9320

Aanderaa WaterLog / DAA MJK

Date: 7/16/2014

Estimate for Service Request #:

306378

Bill To:

Noaa

7600 Sand Point Way N.E.

Wc3

Scott Mckeever

Seattle, Wa-98115

Customer #: 16270

Quoted by: Baxter, Jason

Please Contact me at

Phone #: 937-767-7241 option 4

Fax #:

Email:

repairs@ysi.com

Email/Fax: scott.mckeever@noaa.gov, shawn.sneddon@xyleminc.com

Contact: SCOTT MCKEEVER Phone#: 1-206-5266205

100.76% BATH. TEMP REPORTS 10.09 IN 10.11 DEG C BATH.

Total for this Service Request:

\$1,743.34

SHIPMENT TERMS:

Once approval is received and parts are available.

Purchase order or Prepayment

FINAL TEST - MEETS AADI SPECS

Net 30 days

F.O.B Shipping Point

MasterCard, Visa, and American Express accepted.

FREIGHT TERMS:

Prepaid and added to Invoice

NOTES:

This quote does not include any applicable Taxes, and this quote is valid up to 30 days from the date of issue.





