Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 5584 CALIBRATION DATE: 06-Mar-15

SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS:

g = 4.32884138e-003 h = 6.29314466e-004 i = 1.92771610e-005 j = 1.30008883e-006

ΤU	=	1000.	U

BATH TEMP (ITS-90)	INSTRUMENT FREQ (Hz)	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
-1.5001	2889.635	-1.5001	-0.00005
0.9999	3058.253	1.0000	0.00009
4.5000	3306.158	4.5000	-0.00002
8.0000	3568.267	7.9999	-0.00005
11.4999	3844.997	11.5000	0.00006
14.9999	4136.748	15.0000	0.00006
18.5000	4443.908	18.4999	-0.00013
22.0000	4766.885	21.9999	-0.00005
25.4999	5106.044	25.5000	0.00013
29.0000	5461.741	29.0000	0.00002
32.4999	5834.325	32.4999	-0.00004

Temperature ITS-90 = $1/\{g + h[ln(f_0/f)] + i[ln^2(f_0/f)] + j[ln^3(f_0/f)]\}$ - 273.15 (°C) Residual = instrument temperature - bath temperature

