

SERVICE REPORT

**CUSTOMER INFORMATION** 

# Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

> **Service Request Date** Sales Order

> > PO Number:

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com

1005507650 17-MAY-2019

Name: NOAA Account: 40299841 **David Strausz** 

david.strausz@noaa.gov

1-206-526-4510

**Bill To Address** 7600 SAND POINT WAY NE: SEATTLE,WA,98115,US

**Ship To Address** 7600 SAND POINT WAY NE: SEATTLE,WA,98115,US

### PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

Serial: 16P27024-4139

**Special Notes** 

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service. Replace Antifoulant Device(s).

Problems Found:

The 2-pin and 6-pin connector were found to be damaged.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the 2-pin and 6-pin connector.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed "POST" cruise calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
17628	Bulkhead connector, 6-pin Standard, AG-306-HP-SS	2
17652	Bulkhead connector, 2-pin Standard, XSG-2-BCL-HP-SS	1
SERVICE16	Confirm / recertify SBE 16/16plus/16plusV2. Complete External Inspection. Test All Functions and input channel responses. Calibrate C & T. C&P and recal if necessary. Replace O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2



**SERVICE REPORT** 

**Sea-Bird Electronics, Inc.** 13431 NE 20th Street Bellevue, WA 98005 United States

Phone Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com

**Service Request Date Sales Order** 

1005507650 17-MAY-2019

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



# Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

> Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507650** 17-MAY-2019

## **SERVICE REPORT**

# PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

Serial: 16P60727-6629

**Special Notes** 

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	Confirm / recertify SBE 16/16plus/16plusV2. Complete External Inspection. Test All Functions and input channel responses. Calibrate C & T. C&P and recal if necessary. Replace O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



## Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

# SERVICE REPORT

Phone Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507650** 

Service Request Date Sales Order

17-MAY-2019

## PRODUCT INFORMATION

Item: 16.LEGACY

Item Description: (LEGACY) SBE 16 CT(D)

Serial: 1625591-3114

**Special Notes** 

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Problems Found:

The 6-pin connector was found to have corrosion damage.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the 6-pin connector.

Replaced the lithium back-up battery(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	Confirm / recertify SBE 16/16plus/16plusV2. Complete External Inspection. Test All Functions and input channel responses. Calibrate C & T. C&P and recal if necessary. Replace O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
17628	Bulkhead connector, 6-pin Standard, AG-306-HP-SS	2
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22009	Lithium back-up battery (BR-2/3A-T2SP)	2



**SERVICE REPORT** 

# Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

Service Request Date

Sales Order

Phone +1-425-643-9866 Fax +1-425-643-9954 www.seabird.com

www.seabird.com 1005507650 17-MAY-2019

## PRODUCT INFORMATION

Item: 16.LEGACY

Item Description: (LEGACY) SBE 16 CT(D)

Serial: 1611044-1815

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Problems Found:

The 6-pin connector was found to have corrosion damage.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the 6-pin connector.

Replaced the lithium back-up battery(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	Confirm / recertify SBE 16/16plus/16plusV2. Complete External Inspection. Test All Functions and input channel responses. Calibrate C & T. C&P and recal if necessary. Replace O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
17628	Bulkhead connector, 6-pin Standard, AG-306-HP-SS	1
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22009	Lithium back-up battery (BR-2/3A-T2SP)	2