G								
g		GE Industria	Systems	Functional T	esting Spe	cification		
Renewal Services Louisville, KY			LOU-GE-ATE1					
Test Procedure for a Card tested on the ATE								
DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column								
REV.		DESCRIPTION			GNATURE	REV. DATE		
Α	Initial release			R	R. Duvall	6/19/02		
В	Changed procedure	number and converted	to new format.	R	R. Duvall	06/21/02		
С								
© COP	YRIGHT GENERAL ELECTI	RIC COMPANY						
Hard copies are uncontrolled and are for reference only. PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.								
PREPA R. Du	ARED BY vall	REVIEWED BY	REVIEWE	D BY	Rober o			
DATE 06/07	/02	DATE	DATE		DATE 06/21/02			

LOU-GE-ATE1
REV. B

GE Industrial Systems
Renewal Services
Louisville, KY

Page 2 of 3

Functional test procedure for an ATE tested item.

1. SCOPE

1.1 This is a functional testing procedure for a card or unit on ATE1.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 2.1.1 System documentation
 - 2.1.2 Folder for unit or card being tested

4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken or cracked
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - 4.2.1.5 Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - 4.2.1.8 Printed wire runs burned or damaged

5. **EQUIPMENT REQUIRED**

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1	H033779	ATE1
		Other items as required by ATE test.

LOU-GE-ATE1

REV. B

GE Industrial Systems

Renewal Services
Louis ville, KY

Page 3 of 3

6. TESTING PROCESS

- 6.1 Setup
 - **6.1.1** As required by ATE instructions
- **6.2** Testing Procedure
 - **6.2.1** Identify the test to be used on the ATE by matching the model number with the ones on the system and follow the instructions given after execution.
- 6.3 ***TEST COMPLETE ***

7. NOTES

7.1 None at this time.