

# **GE Power Generation Engineering**

PROCESS SPECIFICATION

Materials and Processes Engineering Schenectady, NY 12345

P3K-AL-0443-A01

### TEST INSTRUCTIONS FOR LOAD LIMIT POSITIONING CIRCUIT

DOCU	MENT REVISIO	ON STATUS: DETERMINED BY THE LAST ENTRY IN THE "REV" A	ND "DATE" COLUMN	
REV.	AN NO.	DESCRIPTION	SIGNATURE	REV. DATE
A	YA00096	SPECIFICATION LISTED IN STEAM TURBINE/GENERATOR INDEX AS "INACTIVE" HAS BEEN FORMALLY REVISED AS "INACTIVE FOR NEW DESIGN". (PR BUDKA)	C.R. Truppe	DEC 0 2 1997
		INACTIVE FOR NEW DESIGN AS OF 12/02/91		

e copyright 1991 general electric company

PROPRIETARY INFORMATION - THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS. EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

P.R. BUDKA

ORIG. ISSUE DATE:

CONT ON SHEET

P3K-AL-0443-A01

TEST INSTRUCTIONS FOR LOAD LIMIT POSITIONING CIRCUIT 1L2-J001

12

FIRST MADE FOR

EHC MARK II (ASSEMBLY DRAWING 118D1335 G1)

REVISIONS

#### I. SCOPE

This instruction outlines the test specification for circuit board 1L2-J001. Reference Board Assembly 118D1335 G1; Schematic 125D5345.

#### II. CIRCUIT DESCRIPTION

SH NO.

This circuit accepts and combines input switching signals from load control and other units of the control system and provides accordingly 115V AC to the load limit set motor drive.

The board contains 24 VDC circuits (TB1, all 5 relay coils and associated circuitry) and 115V 60 HZ AC circuits (TB2, TP3, and 3 transformers, the 2 thyrectors, all relay contacts and associated circuitry). TB3 supplies +125 VDC to K6.

The circuit provides 115V to TB2-21 to increase the load limit set and to TB2-22 to decrease it.

These outputs are determined by two methods of operation involving different inputs:

#### a. MANUAL OPERATION

By applying 24V (through control panel pushbuttons) to relay Kl (decrease) or relay K2 (increase). Manual operation is permitted only when K5 is de-energized or K6 energized, which disables the remote operation.

#### b. REMOTE OPERATION

By applying 115V AC from Plant Communications to TB3-24 (decrease) or TB3-25 (increase). The isolation transformers permit this to be done either by using external source or the 115V provided to Plant Communications through TB3-23 for this purpose.

#### CIRCUIT SPECIFICATIONS

- Before coating the board the eight diodes CR1 CR8 should be checked, one by one to insure redundancy is effective.
- 2. Isolation between circuits.

Resistance between TB1-1 and TB1-2 should be > 1M Ohm Resistance between TB1-1 and TB2-19 should be 1M Ohm Resistance between TB1-2 and TB2-19 should be >1M Ohm Resistance between TB3-26 and TB2-19 should be 1M Ohm Resistance between TB2-18 and TB2-19 should be∠.1 Ohm

COPYRIGHT 1983 GENERAL ELECTRIC CO.

O SEP 21 1977

SEP 22 1977

DIV OR

Schenectady, N.Y.

P3K-AL-0443-AO1

FF-803-WA (2-75) PRINTED IN U.S.A.

CODE IDENT N 6T0

273-314

273-12°

273-7**1** 

273-13

PRINTS TO

APPROVALS

Steam Turbine

LOCATION CONT ON SHEET

SH NO.

+

+

## GENERAL (%) ELECTRIC

P3K-AL-0443-A01

CONT ON SHEET

+

TITLE

CONT ON SHEET

P3K-AL-0443-A01

FIRST MADE FOR

EHC MARK II (ASSEMBLY DRAWING 118D1335 G1)

TEST INSTRUCTIONS FOR LOAD LIMIT POSITIONING CIRCUIT

REVISIONS

### CIRCUIT SPECIFICATIONS (continued)

#### Thyrectors

SH NO.

Resistance between TB2-16 and TB2-18 should be > 100K Ohms Resistance between TB2-17 and TB2-18 should be > 100K Ohms

(These measurements must be done by using a multimeter or other low voltage instrument and testing both polarities).

#### 4. Transformers

Apply 115V 60 HZ between TB2-20 and TB2-19 and measure the voltage between TB3-23 and TB3-26. It should be  $115V \pm 1.5V$ .

Connect TB3-24 and TB3-25 together and apply 115V 60 HZ between these two points and TB3-26. Measure voltages to ground (TB2-19) of TP4 and TP5. Both should be  $115V \pm 1.5V$ .

#### 5. Logic and Path Continuity

Connect TB3-23, TB3-24, and TB3-25 together. Connect two 115V minature lamps to TB2-21 and 22 (other ends of lamps to 115V common). Connect TB1-1 to 24 VDC and TB1-2 to 24 VDC common. Connect TB2-19 to 115V 60 HZ common and TB2-20 to 115V 60 HZ.

Check the logic and path continuity by using the table on page 3.

PRINTS T

FP 2.1 197

Steam Turbine

P3K-AL-0443-A01

Schenectady, N.Y.

LOCATION CONT ON SHEET

+

EV /7 40	-	-1-14			TIT! F				€ EL					CONT ON		443-A01 sh No	o
E. PA					TITLE				—							5	4
	L-044			,	TEST											IRCUIT	
ONT ON SHEET	7	SH NO	4		FIRST	MADE	FUR	EH	C MARI	II	(AS	SEMB	LY I	JKAW LN	<u> 4 1 1 </u>	8D1335 G1)	REVISI
1	i													1		ຫຼຸ ຫຼຸ	
	TP7	0 0 8	7	0		0	0	Ο.		0	0	0			stages input this is		
S	TP6	0	0	7	0		0	0	0		Ö	0	0			(L) (A) (L)	
POINTS	TP 5	0	0	0	7		64	0	0		0	0 0			U 10 1		
	TP4	0	0	0	7		7	0	0		0	0	0			□ <del></del> 1	
TEST		0	7	0	0	0			0	<b>©</b>	0						
IT AT	TP2 I	. 0	2	0		0		0		Ο,	0	0		the so thunder			
OUTPUT	TP1 T	0	0	0	H	<u>-</u>	Н	0	0		0		0		re, en is		
01	H					(TO)										13 LJ	
1	15	0	0	0	0	3-28	0	0	0		0	0	=			<b>~</b> # # # # # # # # # # # # # # # # # # #	
TB1	14	Н	Н	Н	0	and TB3-28	0	н	H		0	7	Н				
AT	13	0	0	0	-		0	0	0		0	0	0			quent Care irs at	
BELOW) OUTPUT	7	.0	0	0	. <del>⊢</del> I	(HI)	⊢	0	0		Н	0	,I			s sec	
	5	0	0	0	H		H	0	0		0	0	0			e is tíal on o	
(SEE NOTES	•					TP3-29		*		TB3-29						The table is seque is essential. Car transition occurs a constraint of th	
E						to				TB				}		The tis estranstrans	
(SE	. [					VDC				from			٠.			6449	
AT TP	22	0	. 8	0	7	+125	2	0	0	VDC 1	0	0	0				
	,,,					1y +											
OUTPUT	21	0	0	7	7	apply	7	0	0	and +125	0	0	0				
-1						and										uo d	
	15		0	0	-31,	0	0	0	TB1-1	0	0	H			Lamp		
TB1	14 1		0	0	TB3-31,	0	0	0	from J	0	H	0	ļ		и 0 0		
APPLY +24 VDC AT TB1	13 1	0	0	0	0	to	0	0	0	)C £1	0	0	0	ŀ		0V 24 VDC 115VAC	
ADC	7 1	0	0	0	0	TB3-30	. 0	. 0	0	4 VDC	н.	0	0				
+24	ဖ	0	0	0	ᆏ			0	0	e +24	0	0	0			9 H 2	
PLY	4	0	0	Н	0	Jumper	0	0	H	Remove	0	0	0			NOTE:	
	m	0	<u></u>	0	O	OVALS	0	0	H	Re	0	0	0			Ž	PRINT
THUUU	CED	SF <sub>Pa</sub>	411	9 <b>77</b>	APPH	OVALS			Turb				DEPT.			-0443-A01	
SUED	JET A	101 W	• .		<u> </u>		S	chen	ectady	, N	.Y.	LOC	ATION	CONT ON	SHEET	<b>5</b> SH I	ODE IDE

+

+

+

+

1EV 0 12	TITLE	•				CONT ON SHE	ET SH I	·5
	TEST INST	RUCTION	S FOR LO	DAD T	IMIT POSI	<b>'</b> ዋፐ በ <b>ለ</b> ፐ ክር	CTRCIITT	
P3K-AL-0443-A01  ONT ON SHEET SH NO.	1L2-J001 FIRST MADE F						118D1335 G	
INT ON SHEET SH NO. 4	THAT MADE P	OR L	IIC PIANK	TT (	ASSEMBLY	DRAWING	118D1335 G	L) REVISION
								AEVISION
							g Mari	
					•			
	•							
PREPARED BY ) Tom	broku				DATE	7-28	7-75	
J. Dombrosk	, ,		<del></del>					i .
EHC DESIGN	ENGINEERING			•			men manakan san	
								L
								ļ
$\Omega$ 1		3 <i>~</i>						ļ
APPROVED BY	Cas	Len_		···	DATE	9-12	- 77	
P.C. Callan	MANAGER ENGINEERING					•	•	
DIO DIOLON					. •		· · · · · · · · · · · · · · · · · · ·	
						•	· · · · · · · · · · · · · · · · · · ·	
•							*	
TEST PROCEDURE	$\sim$ $\alpha$	- 1i					,	
REVIEWED BY ( G).	Deberto	ti.			DATE	5-5	·- 72	1
R. Debertol EHC TEST EN								
ENO TEST EN	GINEBIC						*	
							4, ,	
		,					·	
							* *************************************	
							* •	
							· ·	
3							• • • • • • • • • • • • • • • • • • • •	
							M 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PRINTS
OLACLE SEP 21 1977	APPROVALS	Steam '	l'ur <b>b</b> ine	winter	DIV OR	P3K-4	L-0443-A01	
50 SEP 22 1977	]	Schene	cta <b>dý</b> , N	.Y.	LOCATION			NO. 5
03-WA (2-74)	<u></u>		<del></del>	ī				ODE IDENT

+

+

+