68 A 9 8 9 3 4 8

CONT ON SHEET FL. SH NO. 1

REVISIONS

TITLE TIMED ACCELERATION TEST SPECIFICATION 68A989348

FIRST MADE FOR

.ELEMENTARY -

SH. 3.0

POWER NEUTS 103600AFGD

CONT ON SHEET

FL.

P N 24 +50 VOLTS

P.N 30

-50 VOLTS

P NS 2 AND 50 - COMMON -- 30 VOLT TO PIN 44

LOADS -1500 OHMS, 10 WATTS (PIN 6 TO P N 50)

POT SWI NOTES. SES

CONNECT CARD IN TEST & ROUT AS SHOWN BELOW. SW1 IMEG 30 SW2 16 20 18 40 MED. IMEG 1.5K

SET BINS - SET R43 AND R44 FULL C.W. CLOSE SWI AND SW2. SET 2.5K POT FOR -15V ON POT WIPER . ADJUST TRIMPOT R42 SO THAT CUTPUT VOLTAGE (PIN 50 (+) C N 6 (-)) DOES NOT CHANGE WHEN SW2 IS OPENED. (DO NOT HANG VOLLMETER ON PIN 20) WHEN SETTINE POT.

SET BALANCE - CLOSE SWI AND SW2. SET 2.5K POT FULL CCW. ADJUST TRIMPOT R44 TO 05TA N ZERO VOLTE FROM PIN 20 TO PIN 6.

SET CLAMP - AT SET 2.5K POT INEXTREME COUNTER-CLOCKWISE POSITION. ADJUST TRIMPOT 843 TO CBTAIN 5 M LL VOLTS FROM P N 50 (+) TO P.N 6 (-).

CHECK CHERENT LIMIT - SET 2.5K POT IN EXTREME CLCJKWISE POSITION. SHORT TERMINAL & TO TERM BUL 50. AFTER ONE MINUTE REMOVE THE SHORT. VOLTAGE FROM PIN & TO PIN 50 SHOULD RECOVER 10130 VOLIS.

CHECK TIMING - SET 2.5K POT FULL CCV. OPEN SWITCH SW-1. VOLTAGE FROM PIN 6 TO PIN 50 SHOULD DECAY TO 5 MV IN 30 TO 35 SECONDS. CLOSE SW! , SET 2.5K POT FULL CW. VOLTAGE FROM PIN 6 TO PIN SO SHOULD RECOVER TO 30V IN 30 TO 35 SEC.

PEINTS TO

HADE BY APPROUNTS . e 8 = 9 8 9 3-4 3 level 17, 1964

-밥.