g		GE Energy		Functional	Testing Sp	ecification
	Parts & Rep Louisville, K	air Services Y		LOU	J-GED-IS230J	PDS
	1	est Procedure for an l	IS230SRTDHxA	Mark VIe Assen	nbly.	
DOCU	MENT REVISION STATUS	S: Determined by the last e	ntry in the "REV" a	nd "DATE" column		
REV.		DESCRIPTION			SIGNATURE	REV. DATE
Α	Initial release				J. Francis	03/20/2017
В						
С						
	YRIGHT GENERAL ELECTopies are uncontrolled and are					
MAY N	NOT BE USED OR DISCLOS	THIS DOCUMENT CONTAIN SED TO OTHERS, EXCEPT W	ITH THE WRITTEN	PERMISSION OF GEN	IERAL ELECTRIC	COMPANY.
J. Fra	ARED BY ancis	REVIEWED BY	REVIEWE	א ט א	L. Groves	PKUVAL
DATE		DATE	DATE		DATE	
03/20	)/2017				2/21/2017	

	g	
LOU-GED-IS230JPDS	GE Energy	Page 2 of 3
Rev A	Parts & Repair Services	
	Louisville, KY	

#### 1. SCOPE

1.1 This is a functional testing procedure for an IS230JPDSxxxx MARK VIe assembly.

## 2. STANDARDS OF QUALITY

**2.1** Refer to the current revision of the IPC-A-610 standard for workmanship standards.

# 3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
  - **3.1.1** Check board's electronic folder for more information.

# 4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
  - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.
- **4.2** Equipment Inspection
  - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
    - 4.2.1.1 Wires broken, cracked, or loosely connected
    - 4.2.1.2 Terminal strips / connectors broken or cracked
    - 4.2.1.3 Components visually damaged
    - 4.2.1.4 Capacitors bloated or leaking
    - 4.2.1.5 Solder joints damaged or cold
    - 4.2.1.6 Circuit board burned or de-laminated
    - 4.2.1.7 Printed wire runs / Traces burned or damaged

### 5. EQUIPMENT REQUIRED

**5.1** The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		TOFFEE Test System

LOU-GED-IS230JPDS
Rev A

GE Energy
Parts & Repair Services
Louis ville, KY

Page 3 of 3

# 6. TESTING PROCESS

# 6.1 Testing Procedure



Note: This procedure will be for an entire *IS230JPDSxxxx* assembly. The assembly will be broken down to individually test each sub-assembly separately using its assigned test. The test procedure will be listed for each sub-assembly.

- **6.1.1** Remove the **JPDS** card and test using test procedure LOU-GED-IS200JPDS-A, referring to Models Database for latest revision of test procedure.
- **6.1.2** Remove the **PPDA** PAC Modules and test using test procedure LOU-TOFFEE-IS220PPDA-C, referring to Models Database for latest revision of test procedure.

#### 6.2 \*\*\*TEST COMPLETE \*\*\*

### 7. NOTES

**7.1** None at this time.

# 8. ATTACHMENTS

**8.1** None at this time.