g		GE Energy	Functi	onal Testing Sp	ecification		
Parts & Repair Services Louisville, KY				LOU-UTS-531X307LTBA			
Test Procedure for cards tested on the UTS-3000 Tester							
DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column							
REV. DESCRIPTION				SIGNATURE	REV. DATE		
A	Initial release	<b>D200</b> 1111 11011		E. Rouse	12/3/2010		
	ITIIllai Telease			E. Rouse	12/3/2010		
В							
С							
© COP	YRIGHT GENERAL ELECTF	RIC COMPANY					
Hard copies are uncontrolled and are for reference only.  PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.							
PREPA Eric R	ARED BY Rouse	REVIEWED BY Paul Kelley	REVIEWED BY	QUALITY AP Charlie We			
DATE 12/3/2	2010	<b>DATE</b> 12/3/2010	DATE	<b>DATE</b> 12/3/2010			

GE Energy
Parts & Repair Services
Louisville, KY

# LOU-UTS-531X307LTBA REV. A

# Functional test procedure for a 531X307LTBA card tested on the UTS Test System

### 1. SCOPE

1.1 This is a functional testing procedure for the UTS3000 Tester

# 2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

### 3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
  - **3.1.1** Check board's electronic folder for more information

# 4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
  - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.
- 4.2 Equipment Inspection
  - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
    - 4.2.1.1 Wires broken or cracked
    - 4.2.1.2 Terminal strips / connectors broken or cracked
    - **4.2.1.3** Loose wires
    - 4.2.1.4 Components visually damaged
    - 4.2.1.5 Capacitors leaking
    - 4.2.1.6 Solder joints damaged or cold
    - 4.2.1.7 Circuit board burned or de-laminated
    - 4.2.1.8 Printed wire runs burned or damaged

### 5. EQUIPMENT REQUIRED

COMPANY.

**5.1** The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1	H188701	UTS3000 Tester
1	H188735	LTBA Fixture

g

# LOU-UTS-531X307LTBA REV. A

**GE Energy**Parts & Repair Services
Louisville, KY

Page 3 of 3

# 6. TESTING PROCESS

- 6.1 Setup
  - **6.1.1** Install test fixture H188735.
  - **6.1.2** As required by UTS3000 instructions.
- 6.2 Testing Procedure
  - **6.2.1** Identify the test to be used on the UTS3000 by matching the model number with the ones on the system and follow the instructions given after execution.
- 6.3 \*\*\*TEST COMPLETE \*\*\*
- 7. NOTES
  - 7.1 None at this time.
- 8. Attachments
  - **8.1** None at this time.