PRODUCTION TEST INSTRUCTIONS 20 WOLT POWER SUPPLY CARD 1.0 SCOPE These proceedures cover the infimum requirements for production testing of the subject card. The operating conditions are stated in Sec. 3. For engineering spec refer to 224x360AA. 2.0 INSTRUCTIONS 2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115v AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected across each output the output voltages shall be "Ittimed" to values from 19.90 to 20.07v DC. Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.03 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94v to 138v AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20w resistory between tabs 21 and 26 and a second resistor between tabs 8 and 10.(1) while monitoring the +20v output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30v DC. After the crowbar has tripped the -20v output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network operates. This level should be between 21 and 20v DC. After the crowbar heat ripped day and not to exceed 0.25 ohm. The subject card should contain a rectifier card 199X265AA which meets 15 ohm. The subject card should contain a rectifier card 199X265AA which meets 15 ohm. The subject card should be requalified by Quality Control every eighteen m	RIVA							CONT ON SHEET	TOT .		1
20 YOUT POWER SUPPLY CARD 1.0 SCOPE These proceedures cover the sinimum requirements for production testing of the subject card. The operating conditions are stated in Sec. 3. For engineering spec refer to 224X360AA. 2.0 INSTRUCTIONS 2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected across each output the output voltages shall be "Intimad" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2A3 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 136V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor, between tabs 21 and 26 and a second resistor between tabs 8 and 10.1 While monitoring the 42V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network of the production of the production of the subject card should be requalified by Quality Control every eighteen months or after every 2000 production car	NO. W			TITLE				COMI ON SHEET	FL;	SH NO.	1
These proceedures cover the minimum requirements for production testing of the subject card. The operating conditions are stated in Sec, 3. For engineering spec refer to 224x360AA. 2.0 INSTRUCTIONS 2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected across each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC important: Trim the positive supply first. 2.04 Reducing the load from the level of 263 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10.(1) While monitoring the +20W output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30W DC. After the crowbar has tripped the -20W output should be at less than 1 wolt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network operates. This level should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 3.0 DATA-J 1913 Memory 1913 Memory 1914 M		224	X707AA								
These proceedures cover the testing of the subject card. The operating conditions are stated in Sec. 3. For engineering spec refer to 224x360AA. 2.0 INSTRUCTIONS 2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected ecross each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.01 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10, While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network) are misment begins. Line impedance between rectifier card and ower supply card not to exceed 0.55 ohm. The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 200 AND	CONTO	N SHEET	FL SH NO.	1 FIRST	MADE FOR	19	3x257AAG01				
These proceedures cover the testing of the subject card. The operating conditions are stated in Sec. 3. For engineering spec refer to 224x360AA. 2.0 INSTRUCTIONS 2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected ecross each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.01 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10, While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network) are misment begins. Line impedance between rectifier card and ower supply card not to exceed 0.55 ohm. The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 200 AND	1.0	SCOPE	:							R	EVISIO
testing of the subject card. The operating conditions are stated in Sec, 3. For engineering spec refer to 224x360AA. 2.0 INSTRUCTIONS 2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected scross each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2c3 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistory between tabs 21 and 25 and a second resistor between tabs 8 and 10.1 while monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network) are misment begins. Line impedance between restrifier card and power supply card not to exceed 0.25 onto this test impedance between rectifier card and ower supply card not to exceed 0.25 onto this test impedance between rectifier card and ower supply card not to exceed 0.25 onto this test feet spec; 224x706. The test circuit transformer should be loaks156cA005. 4.0 REQUALTEICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.			-	s cover th	ne .	. minimum r	equirements	for product	ion		
2.01 Before applying power to card, check fuses and add an ammeter at each raw power input. 2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected across each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.03 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 92V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of saction 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10.10 While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm; for this test sheet; 24X706: The test circuit transformer should be 10AX1560AOS. AND The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		testi	ng of the su	ubject car	d. The ope	erating con	ditions are	stated in S	ec.3.	-	
2.02 Voltage to the transformer should be slowly increased to 115V AC. Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28.6 ohms (0.7 ampere) connected across each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.03 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 9AV to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses, Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10. (1) While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 to tab 31. 2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test inpedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X26AAA which meets its test stay contains a rectifier card 193X26AAA which meets its test stay contains a rectifier card 193X26AAA which meets its test stay contains a rectifier card 193X26AAA which meets test test stay contains a rectifier card 193X26AAA which meets its test stay contains a rectifier card 193X26AAA which meets it	2.0	INSTRUCTIONS									
Ammeters should not register any current in excess of 0.1 amperes. 2.03 With loads of 28,6 chms (0.7 ampere) connected across each output the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.03 to zero shall cause an output change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10.10 While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 to tab 31. 2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224x360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed 0.75 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193x268AA which meats its test spec; 224x706: The test circuit transformer should be 104x156CA005. 3.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		2.01 Before applying power to card, check fuses and add an ammeter at each raw power input.									
the output voltages shall be "strimmed" to values from 19.90 to 20.07V DC Important: Trim the positive supply first. 2.04 Reducing the load from the level of 2.63 to zero shall cause an output change of no more than 30 millivolts. 2.05 Wary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10. (1) While monitoring the 420V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224x360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 1932x68AA which meats its test spec; 224x706; The test circuit transformer should be 104x156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		2.02	Ammeters should not register any current in excess of 0.1 amperes.								,
change of no more than 30 millivolts. 2.05 Vary the AC input to the transformer from 94V to 138V AC. The output level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10.10 While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 to tab 31. 2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 24X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed 0.75 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193x268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 3.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		2.03	the output voltages shall be "trimmed" to values from 19.90 to 20.07V DC								· · · · · · · · · · · · · · · · · · ·
level should vary no more than 30 millivolts. 2.06 With the loads of section 2.03 applied and AC inputs at either of the extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10. (1) While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 from tab 31. 2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm, The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		2,04	Reducing the load from the level of 203 to zero shall cause an output change of no more than 30 millivolts.								
extremes of section 2.05, output ripple shall be no more than 30 millivolts peak to peak. 2.07 Disconnect all loads and card fuses. Connect a 100 ohm, 20W resistor between tabs 21 and 26 and a second resistor between tabs 8 and 10. (1) While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 to tab 31. 2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706. The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		2.05	Vary the AC level shoul	input to ld vary no	the transion of the transi	Former from 30 millivo	94V to 138V lts.	AC. The o	utput		}
between tabs 21 and 26 and a second resistor between tabs 8 and 10.(1) While monitoring the +20V output, slowly increase the AC supply. Note the level at which the crowbar network operates. This level should be between 21 and 30V DC. After the crowbar has tripped the -20V output should be at less than 1 volt. (1) Connect tab 26 to tab 31. 2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm; for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm; The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.	· [2.06	extremes of	f section	2.05, outpu	applied an it ripple s	d AC inputs hall be no m	at either o ore than 30	f the		
2.08 Disconnect tab 26 from tab 31 and connect tab 8 to tab 2. Repeat the above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.		2.07	between tab While monit the level a between 21 should be a	s 21 and coring the twhich the and 30V De the the state of the state o	26 and a sec +20V outpu he crowbar to C. After to an 1 volt.	cond resist t, slowly i network ope	or between to ncrease the crates. This	abs 8 and 1 AC supply. level shou	0. ⁽¹⁾ Note 1d be	37	1
above for the negative crowbar network. 3.0 CONDITIONS The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first.			(1) Conne	ct tab 26	to tab 31.					Ni	
The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. TO(1) MADL BY MADL BY APPROVALS		2.08	Disconnect above for t	tab 26 fr he negati	om tab 31 a ve crowbar	nd connect	tab 8 to tal	2. Repeat	the	1 20	0
The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. TO(1) MADL BY MADL BY APPROVALS				•						N	7
The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. TO(1) MADL BY MADL BY APPROVALS										Ì	N.
The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. TO(1) MADL BY MADL BY APPROVALS						, ,				1	90°
The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. TO(1) MADL BY MADL BY APPROVALS		•		_	•	:	•	· · · · · · · · · · · · · · · · · · ·	1	. 2	<u>~</u>
The above tests should be made with the card connected as per Figure 1 of 224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. TO(1) MADL BY MADL BY APPROVALS	3.0	CONDI	TIONS	•						Ŀ	\underline{M}
224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this test Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 5RC TD(I) PRIN	٠,٠									5	n (B
about 10 seconds should be allowed before adjustment begins. Line impedance between transformer and rectifier card should not exceed .075 ohm for this tes Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 5ROWNERS MADE BY APPROVALS		224X360AA at an ambient temperature of from 20 to 30°C. A warm-up time of									•
between transformer and rectifier card should not exceed .075 ohm for this tes Impedance between rectifier card and power supply card not to exceed 0.25 ohm. The test circuit should contain a rectifier card 193X268AA which meets its test spec; 224X706: The test circuit transformer should be 104X156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 5RO PRIN		about 10 seconds should be allowed before adjustment begins. Line impedance								. [
test spec; 224x706: The test circuit transformer should be 104x156CA005. 4.0 REQUALIFICATION The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 5R(TD(I)) APPROVALS		impedance between rectifier card and nower supply card not to owned A 25 at-								l 5	K (B
The subject card should be requalified by Quality Control every eighteen months or after every 2000 production cards, whichever occurs first. 5R(7D(/)) APPROVALS		The rest circuit should contain a recritier card 193876844 which made the								·m. 5	1-(-1)
months or after every 2000 production cards, whichever occurs first. 5R(1) PRIN	4.0	REQUA	<u>LIFICATION</u>				•	f	**	5	P (B
MADE BY SAL APPROVALS APPROVALS		The s	ubject card	should be	requalifie	d by Quali	ty Control e	very eighted	≥n	5	QC.(
MADE BY LI T BECOME SALA B. TOMAN 1915 APPROVALS ON OR					production	cards, wh	ichever occu	rs first.	10(1)		R.(BI
	MADE BY	Srimm 6	1. J. B. 7 (24)	JAJA APPE		PR WARTANCE	DIV OR				

FF-801-WA (1-70) PRINTED IN U.S.A. CODE IDENT N

LOCATION CONT ON SHEET