GENERAL & ELECTRIC

68A993497 CONT ON SHEET 2 TITLE SH NO. TEST INSTRUCTIONS FOR 68A993497 12-1 REGULATOR CONT ON SHEET 2 1C3600SVZA1 sh No. 1 FIRST MADE FOR SPECIFIC TEST REVISIONS CONNECT CIRCUIT PER FIG. 1. IC 3600 SVZA PS2 7,21 CR50 15 SCOPE 39 O TO 3A AMMETER I C3600SVZA 19 35 1 PS1 27 47 COM ISOLATED C18 100.04 POWER SUPPLY FIG. 1 II INVERTER TEST WITH PS1 SET TO ZERO VOLTS, PS2 SET TO +24V: 1. VERIFY PIN 15 IS A 48 VOLT SQUARE WAVE APPROXIMATELY .85 TO 1.0 MS PER CYCLE. 2. VERIFY VOLTAGE CR29 TO COM IS 9.5 TO 10.5 VOLTS D.C. * ٩ı 3. VERIFY VOLTAGE ACROSS C18 IS 5 TO 6 VOLTS D.C. 4. VERIFY VOLTAGE ACROSS C15 IS -5.5 TO -7 VOLTS D.C. 5. VERIFY VOLTAGE ACROSS C22 IS -16 TO -19 VOLTS.

- 6. VERIFY AMMETER READS 7 TO 1.1 AMPS
- 7. REMOVE POWER. CONNECT CATHODE OF TEST DIODE CR51 TO PIN 35 DIRECTLY. REAPPLY POWER. VERIFY AMMETER READS APPROXIMATELY 1/2 OF STEP & REMOVE POWER. RECONNECT CR50 AND 51 PER FIG. 1.

III VOLTAGE REGULATOR CHECK

1. REAPPLY POWER. SHOULD HAVE SAME CURRENT AS STEP II .6. SLOWLY INCREASE PS1 FROM O VOLTS UNTIL AMMETER DROPS TO ZERO.

ADJUST R120 TO CAUSE

THIS TO OCCUR AT 12.0 VOLTS. REMOVE POWER.

2. REMOVE CONNECTION FROM PS1 TO PIN 1. CONNECT PS1 TO PIN 5. APPLY POWER, SLOWLY INCREASE PS1 FROM O VOLTS UNTIL AMMETER DROPS TO O AMPS. VERIFY THIS OCCURS WHEN PS1 IS BETWEEN 27 AND 29 VOLTS. REMOVE POWER. RETURN PS1 TO 0 VOLTS.

PRINTS TO

2520

DL22

								ľ		. •
DARLENE ALLIE	OCH.	i ND	USTRY CONTROL	DIV OR	6.8	A Q (934	9 7		
Detober 10-1964	15	SAL	EM, VIRGINIA		CONT ON S	•	2	SH NO.	1	
FF-803-WF (12-67)			1		1			co	DE IDENT	NO.

+

+

+

GENERAL & ELECTRIC 68 A 9 9 3 4 9 7 CONT ON SHEET FL. SH NO. REV NO. A TITLE TEST INSTRUCTIONS FOR 68 A 9 9 3 4 9 7 12.₩ REGULATOR FL. SH NO. CONT ON SHEET FIRST MADE FOR 1C3600SVZA1 REVISIONS CURRENT LIMIT CHECK 3. REMOVE PS1 FROM PIN 5 AND COM. ADJUST POT R110 ON CARD FULL C.W. CONNECT PS1 WITH NEG. SIDE TO PIN 29 AND POSITIVE SIDE TO PIN 31. CONNECT PIN 35 TO PIN 31. LEAVE PIN 35 CONNECTED TO 47 ALSO. 4. WITH PS1 SET FOR ZERO VOLTS, REAPPLY POWER. AMMETER SHOULD READ AS IN STEP II .6. ADJUST PS1 TO .B5 VOLTS. ADJUST R110 C.C.W. UNTIL AMMETER 0 DROPS TO ZERO AMPS. REDUCE PS1 TO .6 VOLTS. AMMETER SHOULD RETURN TO ORGINIAL CURRENT, INCREASE TO .85 VOLTS, IT SHOULD DROP TO ZERO. REMOVE POWER, DISCONNECT PS1. (NOTE AMMETER MAY RETURN TO ORIGINAL CURRENT WHEN PS1 EQUAL 6 TO .75 VOLTS. IT MUST BE AT ORIGINAL CURRENT WHEN PS1 IS .6 VOLTS, HOWEVER) IV CROWBAR CHECK 1. RECONNECT PS1 PER FIG. 1. CONNECT PIN 37 TO PIN 51 TO COM. CONNECT N PIN 43 TO PIN 1. REAPPLY POWER. VERIFY THAT AMMETER READS AS IN STEP II _6_ CONNECT A MILLIAMMETER (0-50 MA') FROM PIN 49 TO COM. SLOWLY INCREASE PS1 TILL MILLIAMMETER READS > 3 MA, THIS SHOULD OCCUR WHEN PS1 IS 13 TO 17 VOLTS. REMOVE ALL POWER CONNECTIONS. VERIFY R30, R26, R87, R78 ARE CORRECT OHMIC VALUES. V CONNECT +60 VOLTS TO PIN 23, COM TO PIN 47 CONNECT 4.7 KO RESISTOR FROM 9 TO PIN 47 VERIFY THAT PIN 3 READS 44 TO 50 VOLTS. THIS COMPLETES TEST. REMOVE ALL CONNECTIONS. **DL22** 2520

PRINTS TO

MADE BY

DARLENE ALLIE

OC.J.

INDUSTRY CONTROL

DIV OR
DEPT.

G 8 A 9 9 3 4 9 7

SALEM, VIRGINIA

LOCATION CONT ON SHEET

FL. SH NO.

2

FF.803.WF (12.67) PRINTED IN U.S.A.

+

+

CODE IDENT NO