GENERAL 6 ELECTRIC

P3K-AL-0450-A01

REVISIONS

P3K-AL-0450-A01

TITLE

CONT ON SHEET 2 SH NO.

TEST INSTRUCTIONS FOR LOAD RATE/LOAD SET LIMIT LOGIC
CIRCUIT BOARD 1L2-E002 (ASSEMBLY DRAWING 118D1327 G1)

I. SCOPE

CONT ON SHEET ... 2

This instruction outlines the test specifications for circuit board 1L2-E002 (BOARD ASSEMBLY DRAWING - 118D1327 G1) (SCHEMATIC - 117D9986)

EHC MARK II

II. CIRCUIT DESCRIPTION

sh No. 1

This circuit depending on its input switching signals activates the appropriate analog to logic relays which in turn apply the suitable loading rate limits to the load reference amplifier.

The circuit is able to give five output commands:

FIRST MADE FOR

1/2% Loading Rate: 24V at Pin 15

1% Loading Rate: 24V at Pin 14

3% Loading Rate: 24V at Pin 8

5 to 10% Loading Rate: OV at Pin 20

Very High Loading Rate: 24V at Pin 32

The first four commands are selected through pushbuttons which apply momentarily 24V to pin 22, 5, 7, and 27. The first three pushbuttons are powered from the board itself (Pin 26). Depressing any pushbutton imposes the corresponding command and clears the previous one. The pushbuttons become inoperative and a 10% loading rate command is given in remote auto or remote operation modes (24V at Pin 28.)

When the main circuit breaker is open (24V at Pin 31) the very high loading rate command is given (24V at Pin 32) and the pushbuttons become inoperative. (A 10% rate command is simultaneously given but this is overriden by the very high rate command inside the analog circuit).

III. CIRCUIT SPECIFICATIONS

- 1. Before coating the board, each of the 34 diodes should be checked to insure that redundancy is effective.
- 2. Connect ground to pin 40 and +24 VDC to Pin 38. Connect 24V 20 MA lamps to pins 15, 14, 8, 20, 32, 28, 26, 2, 3, 4, 21, 23, 25.

The logic and path continuity should conform with the following table:

D.Mone May 27, 1976

Steam Turbine

DIV OR
P3K-AL-0450-A01
Schenectady, N.Y. Location Cont on Sheet 2 Sh No. 1

810

CODE IDENT NO.

273-2 273-12⁶

273-138 273-221

273-227 273-71^{3,}

P3K-AL-0450-A01

CONT ON SHEET TITLE TEST INSTRUCTIONS FOR LOAD RATE/LOAD SET LIMIT LOGIC P3K-AL-0450-A01 (ASSEMBLY DRAWING 118D1327 G1) CIRCUIT BOARE 1L2-E002 FIRST MADE FOR EHC MARK II SH NO.

™.Mone 27, May ISSUED

Steam Turbine

Schenectady, N.Y.

APPROVALS

DIV OR ---- DEPT.

P3K-AL-0450-A01

LOCATION CONT ON SHEET

+

+

PRINTS TO

4

TITLE

CONT ON SHEET TEST INSTRUCTION FOR LOAD RATE/LOAD

P3K-AL-0450-A01

CONT ON SHEET 4 SH NO.

SET LIMIT LOGIC FIRST MADE FOR

MK II

REVISIONS

TEST INSTRUCTIONS

1L2-E002

Assembly Schematic 118D1327

117D9986

PROCEDURE:

- A. Refer to P3K-AL-0494-A02 for test circuits, equipment list, and set up instructions.
- Table A provides the step by step procedure to follow in testing this circuit.
- Table B provides a step by step description of input voltages (to use as a troubleshooting aid).

PRINTS TO

MADE BY May 27, 1976 D.Mone ISSUED MAY 27 1976

Steam Turbine Schenectady

APPROVALS

DIV OR

P3K-AL-0450-A01

LOCATION CONT ON SHEET

FF-803-WA (4-73) PRINTED IN U.S.A.

GENERAL & ELECTRIC

P3K-AL-0450-A01

CONT ON SHEET 5

SH NO. 4

P3K-AL-0450-A01

REY O

TITLE

TEST INSTRUCTION FOR LOAD RATE/ LOAD SET LIMIT LOGIC

ACTION		VOLTAGE AT PINS										
	2	3	4	5	7	8	14	15	20	21		
STEP 1 INIT COND						-			ļ	<u> </u>	_	
STEP 2 APP P 6	В	В	В	`						В		
STEP 3 REM P 6									ļ			
STEP 4 APP P 9											-	
STEP 5 REM P 9											_	
STEP 6 APP P 12												
STEP 7 REM P 12									-		-	
STEP 8 APP P 38									ļ	В	-	
STEP 9 APP P 31										Ø	-	
STEP 10 REM P 31				·						В	-	
STEP 11 APP P 28										Ø		
STEP 12 REM P 28										В		
STEP 13 APP P 15	E				Ø	Ø			A	Ø		
STEP 14 REM P 15	E				Ø	Ø			A	Ø	-	
STEP 15 APP P 27	Ø				Ø	Ø			Ø	В .		
STEP 16 REM P 27	Ø				Ø	Ø			Ø	В	-	
STEP 17 APP P 15												
STEP 18 REM P 15			· · · · · · · · · · · · · · · · · · ·									
STEP 19 APP P 14 STEP 20 REM P 14						:					-	
STEP 21 APP P 27 STEP 22 REM P 27											<u> </u>	
STEP 22 REM P 27 STEP 23 APP P 15				· · · · · · · · · · · · · · · · · · ·				<u> </u>				
STEP 24 REM P 15	-											
STEP 25 APP P 8												
SIEL 77 WLL L O				· · · · · ·			······································				PRINTS	

Schenectady

MAY 27 1976

ISSUED

sh no. 4

LOCATION CONT ON SHEET

GENERAL (ELECTRIC

P3K-AL-0450-A01

CONT ON SHEET 6 REV O TITLE TEST INSTRUCTION FOR LOAD RATE/ LOAD SET LIMIT LOGIC P3K-AL-0450-A01 sh No. 5 CONT ON SHEET 6 FIRST MADE FOR MK II REVISIONS ACTION VOLTAGE AT PINS 2 3 4 7 14 15 2Ø | 21 5 STEP 26 REM P 8 STEP 27 APP P 27 STEP 28 REM P 27 Ø Ø Ø Α STEP 29 APP P 14 C E С Ø Ø Ø STEP 3Ø REM P 14 Ε Α STEP 31 APP P 27 Ø Ø Ø Ø В STEP 32 REM P 27 Ø Ø Ø В STEP 33 APP P 14 C C STEP 34 REM P 14 Ø STEP 35 APP P 15 Ø STEP 36 REM P 15 STEP 37 APP P 27 REM P 27 STEP 38 STEP 39 APP P 14 C STEP 40 REM P 14 C STEP 41 APP P 8 Ø Ø STEP 42 REM P 8 STEP 43 APP P 27 STEP 44 REM P 27 Ø STEP 45 APP P 8 Ø E C A Ø Ø Ø Ø A STEP 46 REM P 8 E C Ø Ø Ø Ø STEP 47 APP P 27 Ø В STEP 48 REM P 27 Ø Ø Ø Ø Ø В C STEP 49 APP P 8 STEP 50 REM P 8 \mathbf{C} PRINTS TO D.Mone May 27, 1976 APPROVALS P3K-AL-0450-A01 DIV OR Turbine _ DEPT. ISSUED PAY 27 1976 Schenectady sh No. 5 LOCATION CONT ON SHEET

PP-803-WA (8-74) PRINTED IN U.S.A.

+

+

CODE IDENT NO.

GENERAL & ELECTRIC P3K-AL-0450-A01 CONT ON SHEET 7 SH NO. 6 TITLE TEST INSTRUCTION FOR LOAD RATE/ P3K-AL-0450-A01 LOAD SET LIMIT LOGIC MK II CONT ON SHEET 7 BH NO. FIRST MADE FOR REVISIONS ACTION VOLTAGE AT PINS 2Ø | 21 2 3 8 14 15 4 7 5 1 Ø STEP 31 APP P 15 Ø STEP 52 REM P 15 STEP 53 APP P 27 STEP 54 REM P 27 STEP 55 APP P 8 C

C STEP 56 REM P 8 STEP 57 APP P 14 Ø STEP 58 REM P 14 Ø STEP 59 APP P 27 STEP 60 REM P 27 STEP 61 REM P 38 PRINTS TO

MADE BY D.Mone May 27, 1976 ISSUED MAY 27 1976

APPROVALS

Turbine Schenectady DIY OR

P3K-AL-0450-A01

LOCATION CONT ON SHEET 7 sh No. 6

GENERAL (%) ELECTRIC

P3K-AL-0450-A01 CONT ON SHEET 8 SH NO. 7 TITLE TEST INSTRUCTION FOR LOAD RATE/LOAD P3K-AL-0450-A01 SET LIMIT LOGIC MK II ян но. 7 CONT ON SHEET 8 FIRST MADE FOR REVISIONS ACTION VOLTAGE AT PINS 22 23 25 26 32 STEP 1 INIT COND STEP 2 APP P 6 В В STEP 3 REM P 6 STEP 4 APP P 9 В. STEP 5 REM P 9 STEP 6 APP P 12 STEP 7 REM P 12 STEP 6 APP P 38 Α STEP 9 APP P 31 С Ø STEP 10 REM P 31 A STEP 11 APP P 28 Ø C STEP 12 REM P 28 Ø STEP 13 APP P 15 С STEP 14 REM P 15 C STEP 15 APP P 27 Ø STEP 16 REM P 27 Ø STEP 17 APP P 15 C STEP 18 REM P 15 STEP 19 APP P 14 Ø STEP 20 REM P 14 Ø STEP 21 APP P 27 STEP 22 REM P 27 STEP 23 APP P 15 C STEP 24 REM P 15 С STEP 25 APP P 8 Ø PRINTS TO MADE BY APPROVALS P3K-AL-0450-A01 DIV OR D. Mone May 27, 1976 Turbine Schenectady MAY 27 1978

de Br

LOCATION CONT ON SHEET 5H NO.

GENERAL % ELECTRIC P3K-AL-0450-A01 CONT ON SHEET 9 SH NO. 8 TITLE TEST INSTRUCTION FOR LOAD RATE/LOAD P3K-AL-0450-A01 SET LIMIT LOGIC MK II CONT ON SHEET 9 ян No. 8 FIRST MADE FOR REVISIONS VOLTAGE AT PINS ACTION 22 23 25 26 32 STEP 26 REM P 8 Ø STEP 27 APP P 27 STEP 28 REM P 27 STEP 29 APP P 14 STEP 30 REM P 14 STEP 31 APP P 27 STEP 32 REM P 27 STEP 33 APP P 14 STEP 34 REM P 14 STEP 35 APP P 15 STEP 36 REM P 15 STEP 37 APP P 27 STEP 38 REM P 27 STEP 39 APP P 14 STEP 40 REM P 14 STEP 41 APP P 8 STEP 42 REM P 8 STEP 43 APP P 27 STEP 44 REM P 27 STEP 45 APP P 8 STEP 46 REM P 8 STEP 47 APP P 27 STEP 48 REM P 27 STEP 49 APP P 8 STEP 50 REM P 8 PRINTS TO D.Mone May 27, 1976 APPROVALS DIY OR P3K-AL-0450-A01 Turbine ISSUED 144 27 1976 LOCATION CONT ON SHEET 9 SH NO. 8

PT-803-WA (8-74)

+

+

CODE IDENT NO.

GENERAL & ELECTRIC P3K-AL-0450-A01 CONT ON SHEET 10 SH NO. 9 NO. TITLE TEST INSTRUCTION FOR LOAD RATE/LOAD P3K-AL-0450-A01 SET LIMIT LOGIC CONT ON SHEET 10 SH'NO. MK II FIRST MADE FOR REVISIONS ACTION VOLTAGE AT PINS 22 23 25 26 32 STEP 51 APP P 15 STEP 52 REM P 15 STEP 53 APP P 27 STEP 54 REM P 27 STEP 55 APP P 8 STEP 56 REM P 8 STEP 57 APP P 14 STEP 58 REM P 14 STEP 59 APP P 27 STEP 60 REM P 27 STEP 61 REM P 38

+

+

D.Mone May 27, 1976

MAY 27 1976

APPROVALS

Turbine Schenectady

DIV OR

P3K-AL-0450-A01

LOCATION CONT ON SHEET 10 SH NO. 9

PRINTS TO

P3K-AL-0450-A01

CONT ON SHEET 11 sh no. 10 TITLE TEST INSTRUCTION FOR LOAD RATE/LOAD

ONT ON SHEET 11 SH NO. 10	T IFIR	ST MADE	L FUR		KII			·····	***************************************		REVISI	
ACTION		INPUT AT PINS										
	6	8	9	12	14	15	27	28	31	38	_	
STEP 1											-	
STEP 2 APP P 6	х											
STEP 3 REM P 6												
STEP 4 APP P 9			х .		ļ						_	
STEP 5 REM P 9											_	
STEP 6 APP P 12				X								
STEP 7 REM P 12												
STEP 8 APP P 38										х		
STEP 9 APP P 31									х	х		
STEP 10 REM P 31										Х		
STEP 11 APP P 28								Х		х		
STEP 12 REM P 28				·		·				х		
STEP 13 APP P 15					,	х				х		
STEP 14 REM P 15		-								X		
STEP 15 APP P 27		•					X			X		
STEP 16 REM P 27						i 				х		
STEP 17 APP P 15					·	х				Х		
STEP 18 REM P 15										х		
STEP 19 APP P 14					Х					Х		
STEP 20 REM P 14										Х		
STEP 21 APP P 27							Х			х		
STEP 22 REM P 27										Х		
STEP 23 APP P 15						Х				Х		
STEP 24 REM P 15										Х		
STEP 25 APP P 8		X								X		

D.Mone May 27, 1976 ISSUED MAY 27 1976

Turbine Schenectady

A

DIV OR

LOCATION

P3K-AL-0450-A01

CONT ON SHEET

SH NO.

PP-BO3-WA [8-74] PRINTED IN U.S.A.

GENERAL (%) ELECTRIC

P3K-AL-0450-A01

12 CONT ON SHEET

11

REV (P3K-AL-0450-A01

TITLE
TEST INSTRUCTION FOR LOAD RATE/LOAD
SET LIMIT LOGIC

ACTION				TNIT	UT AT I	OTNIC					REVISIO
				1		<u> </u>	1	1	1		-
	6	8	9	12	14	15	27	28	31	38	
STEP 26 REM P 8				-				<u> </u>	ļ ·	X	
STEP 27 APP P 27							X				
STEP 28 REM P 27				·						Х	
STEP 29 APP P 14			-	<u>.</u>	Х		ļ			· X	
STEP 3∅ REM P 14										х	
STEP 31 APP P 27							х			Х	pplint 200 mart mine in mine (Million program
STEP 32 REM P 27						,				х	
STEP 33 APP P 14					x					X	
STEP 34 REM P 14										Х	
STEP 35 APP P 15						х				х	
STEP 36 REM P 15										Х	
STEP 37 APP P 27							Х			Х	
STEP 38 REM P 27										Х	
STEP 39 APP P 14					Х					Х	
STEP 40 REM P 14					·					X	
STEP 41 APP P 8		· X					·			· X	
STEP 42 REM P 8										Х	,
STEP 43 APP P 27			1				Х			Х	
STEP 44 REM P 27										Х	
STEP 45 APP P 8		x								X	
STEP 46 REM P 8			 							X	
STEP 47 APP P 27			1				X			X	
STEP 48 REM P 27								·		X	
STEP 49 APP P 8		X								X	
STEP 5Ø REM P 8										- X	
		1 .	<u> </u>	<u> </u>	! !						PRINTS T

Schenectady

MAY 27 1976

ISSUED

SH NO.

LOCATION CONT ON SHEET

GENERAL (%) ELECTRIC P3K-AL-0450-A01 CONT ON SHEET 13 REY O TITLE TEST INSTRUCTION FOR LOAD RATE/LOAD P3K-AL-045Ø-A01 SET LIMIT LOGIC 12 MK II CONT ON SHEET 13 FIRST MADE FOR SH NO. REVISIONS INPUT AT PINS ACTION 9 28 6 8 12 14 15 27 31 38 X STEP 51 APP P 15 STEP 52 REM P 15 Х STEP 53 APP P 27 Х X STEP 54 REM P 27 X STEP 55 APP P 8 X X STEP 56 Х REM P 8 APP P 14 X Х STEP 57 STEP 58 REM P 14 X STEP 59 APP P 27 Х Х STEP 6Ø REM P 27 X STEP 61 REM P 38

PF-803-WA (8-74) PRINTED IN U.S.A.

A S

+

CODE IDENT NO.

CODE IDENT NO.

REV O	TITLE		CONT ON SHEET	sн no. 13
P3K-AL-0450-A01	TEST INSTRU	CTIONS FOR LOAD RAT	E/LOAD SET LIMIT LOGIC	C
CONT ON SHEET - SH NO. 1	3 CIRCUIT BOA FIRST MADE FO	RD 1L2-E002 (ASS R EHC MARK II	EMBLY DRAWING 118D132	/ G1)
	productiva de la companya de la comp			REVISION
				·
0 11			11/01/20	_
PREPARED BY	Similar		date <u>4/24/75</u>	
M.J. Šin			•	
EHC DESI	GN ENGINEERING	•		
			•	
-	0 1 01			
APPROVED BY	Calla		DATE 5-22-7	6
	lan - MANAGER			
EHC DESI	GN ENGINEERING	•	•	
·				· · · · · · · · · · · · · · · · · · ·
				į
THE PROCEDURE				
TEST PROCEDURE PREPARED BY	1 Bugg		DATE 5/20/76	,
C. Bugg	25			
	ENGINEER			
		•		
TEST PROCEDURE		•	The last	
APPROVED BY	J Sinden		DATE 5/20/76	
M.J. Sin	doni GN ENGINEERING	•		
BIO DESI	GN ENGINEERING		•	
	•	•		
.•				,
		•		2000
MADE RY	APPROVALS		· · · · · · · · · · · · · · · · · · ·	PRINTS TO
Mone May 27, 1976	ALLOUALS	Steam Turbine	DIV OR P3K-AL-0450-A	NO1
SSUED 1947 1076		Schenectady N V	LOCATION CONT ON SHEET	sh NO. 13

FF-803-WA (5-74) PRINTED IN U.S.A.