| g | GE Energy | Functional Testing Specification |
|---|---|----------------------------------|
| | | |
| | Parts & Repair Services Louisville. KY | LOU-GED-DS3800NHVG |

Test Procedure for a High Voltage Card

| DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column | | | | |
|---|---|------------|-----------|--|
| REV. | DESCRIPTION | SIGNATURE | REV. DATE | |
| A | Initial release written for DS3800NHVG. | D. Laemmle | 10/14/02 | |
| | | | | |
| В | Procedure was separated unto itself | D. Laemmle | 3/18/09 | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | 1 | | |

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

| PREPARED BY D. Laemmle | REVIEWED BY | REVIEWED BY | QUALITY APPROVAL Charlie Wade |
|------------------------|-------------|-------------|----------------------------------|
| DATE 10/14/2002 | DATE | DATE | DATE 3/18/2009 |

LOU-GED-DS3800NHVG REV. B

GE Energy Parts & Repair Services Louisville, KY Page 2 of 6

Functional test procedure for High Voltage Card

1. SCOPE

1.1 This is a functional testing procedure for a High Voltage Card

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 3.1.1 UUT documentation folder

4. ENGINEERING REQUIREMENTS

- **4.1** Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- **4.2** Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken or cracked
 - **4.2.1.2** Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - **4.2.1.5** Capacitors leaking
 - **4.2.1.6** Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - **4.2.1.8** Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

| Qty | Reference # | Description |
|-----|-------------|--|
| 1 | | Fluke 85 DMM (or Equivalent) |
| 1 | | O-Scope |
| 1 | | 115 VAC line cord |
| 1 | | 28 VDC Power Supply |
| 1 | | SCR Firing Box |
| 1 | | Digital Thermometer (only cards with temperature sensor circuit) |

6. TESTING PROCESS

- **6.1** Attenuator Resistor Test (Resistive)
 - **6.1.1** Using the DMM verify the resistor values in table 1.

| DS3800NHVG | Point A | Point B | Value |
|--------------------|---------|---------|----------------|
| Circuit # 1 | JE-8 | JA-32 | 996K +/4% |
| Circuit # 2 | JG-8 | JA-21 | 996K +/4% |
| Circuit # 3 | JH-1 | JA-27 | 996K +/4% |
| Circuit # 4 | JJ-3 | JA-19 | 996K +/4% |
| Circuit # 5 | JK-3 | JA-28 | 996K +/4% |
| Circuit # 6 | JH-8 | JA-29 | 996K +/4% |
| Circuit # 7 | JK-8 | JA-23 | 996k +/4% |
| Circuit # 8 | JA-30 | JA-23 | 10k +/1% |
| Circuit # 9 | JA-30 | JA-29 | 10k +/1% |
| Circuit # 10 | JA-30 | JA-28 | 10k +/1% |
| Circuit # 11 | JA-30 | JA-19 | 10K +/1% |
| Circuit # 12 | JA-30 | JA-27 | 10K +/1% |
| Circuit # 13 | JA-30 | JA-21 | 10K +/1% |
| Circuit # 14 | JA-30 | JA-32 | 10K +/1% |
| Circuit # 15 | JA-30 | JE-8 | 1.006 meg +/5% |
| JT-1 to above pins | | | Open |

Table 1

LOU-GED-DS3800NHVG REV. B

GE Energy Parts & Repair Services Louisville, KY Page 4 of 6

6.2 CT INPUT TEST: (NHVG)

(Caution: Do not leave power applied for extended period for this test: 1-2 seconds)

- 6.2.1 Connect a voltmeter from JA34 (+) to JA33 (ACOM). Apply +22VDC thru a 10 ohm 10 watt resistor to JC1 with the low side connected to JC2. The voltage at JA34 should go to +16.4 +/- .5VDC. Reverse input polarity and the output at JA34 should be the same. Remove power.
- **6.2.2** Move (+) input to JC4 and low side to JC3 and apply +22VDC. JA34should go to +16.4 +/- .5VDC Reverse input polarity and JA34 should still read +16.4 +/- .5VDC. Remove input power.

6.3 Temperature Sensor test (NHVG)

6.3.1 Apply N15 (-15+/- .1VDC) to JA18 with ACOM to JA31. Wait 2 or 3 minutes for the sensors to stabilize, and then measure the test room ambient temperature near the card under test with a test thermometer (+/- ½ degree C. Determine the calibration setpoint from Table 1 and adjust R2 until the voltage at JA16 is within +/- .010VDC of the setpoint value. SPECIAL NOTE: M1 AND M2 MUST BE SHIELDED FROM ALL AIR DRAFTS TO INSURE PROPER CALIBRATION. ALSO VERIFY M1 AND M2 ARE MOUNTED CORRECTLY PER DS3800NHVG SH. 6BB.

| Temp. Range | Temp. Range | Cal. Setpoint |
|---------------|-----------------|---------------|
| From | TO | |
| 18°C (64.4°F) | 19°C (66.1°F) | -3.980 VDC |
| 19°C (66.2°F) | 20°C (67.9°F) | -3.995 VDC |
| 20°C (68.0°F) | 21°C (69.7°F) | -4.008 VDC |
| 21°C (69.8°F) | 22°C (71.5°F) | -4.022 VDC |
| 22°C (71.6°F) | 23°C (73.3°F) | -4.035 VDC |
| 23°C (73.4°F) | 24°C (75.1°F) | -4.049 VDC |
| 24°C (75.2°F) | 25°C (76.9°F) | -4.063 VDC |
| 25°C (77.0°F) | 26°C (78.7°F) | -4.078 VDC |
| 26°C (78.8°F) | 27°C (80.5°F) | -4.090 VDC |
| 27°C (80.6°F) | 28°C (82.3°F) | -4.104 VDC |
| 28°C (82.4°F) | 28.9°C (84.2°F) | -4.118 VDC |

Table 2A

LOU-GED-DS3800NHVG REV. B

GE Energy Parts & Repair Services Louisville, KY Page 5 of 6

- **6.3.2** Adjust R3 for 0 +/- .005VDC between JA15 and JA16. Connect a 1K +/- 1% resistor from JA17 to JA 18. Wait 2 minutes for sensors to settle.
- **6.3.3** Read the voltage between JA15 and JA16 for .27 +/- .05VDC. Remove power and connections.

6.4 Firing Circuit & LED Test

6.4.1 Use the information in table 3 to apply a non-isolated negative pulse from the SCR Firing box to each circuit and verify with the scope a controllable pulse train output on each circuit. (Reference Figure 1). See notes 1&2 for amplitude.

| DS3800NHVG | SCR Box | SCR | Scope + | Scope | 28 VDC + | Notes |
|-------------|---------|-------|---------|-------|----------|-------|
| | COM | Box | | - | | |
| | | NEG | | | | |
| Circuit # 1 | JA-3 | JA-4 | JE-1 | JE-2 | JA-1 | 1,2 |
| Circuit # 2 | JA-5 | JA-6 | JF-1 | JF-3 | JA-1 | 1,2 |
| Circuit # 3 | JA-7 | JA-8 | JG-3 | JG-2 | JA-1 | 1,2 |
| Circuit # 4 | JA-9 | JA-10 | JH-2 | JH-1 | JA-1 | 1,2 |
| Circuit # 5 | JA-11 | JA-12 | JJ-1 | JJ-3 | JA-1 | 1,2 |
| Circuit # 6 | JA-13 | JA-14 | JK-2 | JK-3 | JA-1 | 1,2 |

Table 3

Note 1: NHVG amplitude is 17 volts. Note 2: 28 VDC COM to SCR Box COM

6.5 ***TEST COMPLETE *** SEAL POTS ON TEMP SENSOR CARDS


LOU-GED-DS3800NHVG REV. B GE Energy Parts & Repair Services Louisville, KY Page 6 of 6

7. NOTES

Output voltages (Waveforms) of gate circuits are measured with output unloaded.

8. Oscilloscope Verification Examples:





DS3800NHVG

17V Peak 5V/Div

.5ms/Div