!			al Systems	· anotional	Testing Spe	cincation	
Renewal Services Louisville,KY			LOU-GED-DS3820FE1				
Test Procedure for a DS3820FE1							
DOCUME	ENT REVISION STATUS: D	etermined by the last e	ntry in the "REV" ar	nd "DATE" column			
REV.		DESCRIPTION			SIGNATURE	REV. DATE	
A	Initial release				J. Wychulis	07/26/02	
В							
С							
© COPYR	RIGHT GENERAL ELECTRIC	COMPANY					
PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.							
PREPAR J. Wych		REVIEWED BY	REVIEWE	D BY	QUALITY APP	PROVAL Dunll	
DATE 25JUL0		DATE	DATE		DATE 07/26/02	C MAN TO	

Е

FE1

g

LOU-GED-DS3820FE1 REV. A

GE Industrial Systems Renewal Services Louisville, KY

Page 2 of 4

Functional test procedure for a DS3820 FE1 assembly

1. SCOPE

1.1 This is a functional testing procedure for a DS3820FE1 assembly.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 3.1.1 DS3820FE1 documentation folder

4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken or cracked
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - 4.2.1.5 Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - 4.2.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 85 DMM (or Equivalent)
1		O Scope
1		Inductive Load
1		480 VAC Power Source

g		
LOU-GED-DS3820FE1	GE Industrial Systems	Page 3 of 4
REV. A	Renewal Services	
	Louisville, KY	

6. <u>TESTING PROCESS</u>

- 6.1 Setup
 - **6.1.1** 480vac to L1,L2,L3 in

inductive load to TB1-3

- 6.2 Testing Procedure
 - 6.2.1 Power up unit
 - 6.2.2 Output should be 300vdc +/- 30v
 - **6.2.3** Check for wave form on scope
- 6.3 ***TEST COMPLETE ***

7. NOTES

8. Oscilloscope Verification Examples:

Fig. 1




Fig. 2

	g	
LOU-GED-DS3820FE1	GE Industrial Systems	Page 4 of 4
REV. A	Renewal Services	
	Louisville, KY	

