g	GE Energy	Functional Testing Specification
	Inspection & Repair Services Louisville, KY	LOU-GEF-1050KYBD

Test Procedure for 1050T&MC KEYBOARD

REV.	DESCRIPTION	SIGNATURE	REV. DATE
Α	Initial release	Rick Diercks	01/02/2009
В			
С			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

PREPARED BY Rick Diercks	REVIEWED BY	REVIEWED BY	QUALITY APPROVAL Charlie Wade
DATE 01/02/2009	DATE	DATE	DATE 1/2/2009

g

LOU-GEF-1050KYBD REV. A

GE Energy Inspection & Repair Services Louisville, KY Page 2 of 6

Functional test procedure for 1050T & MC Keyboards

1. SCOPE

1.1 This specification provides the Engineering Requirements for testing the 1050T&MC Keyboards. The process applies 1050T 44B294346-G01-G05 and 1050MC 44B294321-G01 Keyboards.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1 44C285479 KBLA1 Schematics **3.1.2 44C285863 KBLA1** Schematics

4. ENGINEERING REQUIREMENTS

4.1 Description

The 1050T, MC Keyboard is the manual Data input for 1050T and MC Controls.

- 4.2 Equipment Cleaning
 - **4.2.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.3 Equipment Inspection
 - **4.3.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.3.1.1 Wires broken or cracked
 - 4.3.1.2 Terminal strips / connectors broken or cracked
 - **4.3.1.3** Loose wires
 - 4.3.1.4 Components visually damaged
 - 4.3.1.5 Capacitors leaking
 - 4.3.1.6 Solder joints damaged or cold
 - 4.3.1.7 Circuit board burned or de-laminated
 - 4.3.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1	1050T&MC Keyboard Tester	Keyboard tester

LOU-GEF-1050KYBD REV. A

GE Energy Inspection & Repair Services Louisville, KY

Page 3 of 6

6. TESTING PROCESS

- **6.1** Keyboard Data Test
 - **6.1.1** Turn On/Off SW to off and plug in tester.

g

- **6.1.2** Connect MC or T Keyboard to tester via proper cable to KBAPL connector.
- 6.1.3 Turn on Tester (**Note if it is a 1050T Keyboard all 5-test lamps should come on if not turn off Tester, KBLA board is bad).
- **6.1.4** Check each pushbutton using the coding charts below

Code for 1050 T Keyboard 44B294346-G01 thru G05

COU	e ioi ioso i keybo	aru 44L	234340-G01 till t	1 003	
	Code for 1050	T Keyb	oard 44B294346-	G01	
/	0	1	2-4-8	RS1	2-4-8
N	1	2	1-4-8	RS2	1-4-8
G	1-2	3	4-8	RS3	4-8
X	2	4	1-2-8	RS4	1-2-8
Ζ	2-4	5	2-8	RS5	2-8
I	1-2-4	6	1-8	RS6	1-8
K	1-4	7	8	RS7	1-2-4
R	4	8	1-2-4	RS8	1-4
F	4-8	9	2-4	RS9	1-2
S	1-4-8	0	1-2-4-8		
Т	1-2-4-8	+	4		
Н	2-4-8	-	1-4		
М	2-8		1-2		
\$	1-2-8				
L	1-8				

g

LOU-GEF-1050KYBD REV. A

GE Energy Inspection & Repair Services Louisville, KY Page 4 of 6

Code for 1050 T Keyboard 44B294346-G02

	Code for 1050 T	Keybo	ard 44B294346-	G02	
/	0	1	2-4-8	RS1	2-4-8
N	1	2	1-4-8	RS2	1-4-8
Ο	1-2	3	4-8	RS3	4-8
G	1-2-16	4	1-2-8	RS4	1-2-8
X	2-16	5	2-8	RS5	2-8
Ζ	16	6	1-8	RS6	1-8
U	4-16	7	8	RS7	1-2-4
W	2-4-16	8	1-2-4	RS8	1-4
I	1-2-4-16	9	2-4	RS9	1-2
K	1-4-16	0	1-2-4-8		
R	1-4	+	4		
F	4		1-4		
S	4-8		1-2		
T	1-4-8				
Н	1-2-4-8				
M	1-2-4				
L	2-4				
\$	2-4-8				

Code for 1050 T Keyboard 44B294346-G03

	Code for 1050 T			G03	
/	0	1	2-4-8	RS1	2-4-8
N	1	2	1-4-8	RS2	1-4-8
G	1-2	3	4-8	RS3	4-8
Н	1-2-16	4	1-2-8	RS4	1-2-8
X	2-16	5	2-8	RS5	2-8
Z	16	6	1-8	RS6	1-8
U	4-16	7	8	RS7	1-2-4
W	2-4-16	8	1-2-4	RS8	1-4
I	1-2-4-16	9	2-4	RS9	1-2
K	1-4-16	0	1-2-4-8		
Р	1-4	+	4		
R	4	-	1-4		
F	4-8		1-2		
E	1-4-8				
S	1-2-4-8				
Т	1-2-4				
D	2-4				
M	2-4-8				
L	2-8				

LOU-GEF-1050KYBD

REV. A

GE Energy
Inspection & Repair Services
Louisville, KY

Page 5 of 6

\$ 1-2-8

Code for 1050 T Keyboard 44B294346-G(Code	for 10	50 T Ke	vboard 4	14B29434	6-G0
---------------------------------------	------	--------	---------	----------	----------	------

Oodc 1	or rusu i Keyboar	u TTDES	1010 000		
	Code for 1050 T	<u>Keyboar</u>	d 44B294346-0	3 05	
/	0	1	2-4-8	RS1	2-4-8
N	1	2	1-4-8	RS2	1-4-8
G	1-2	3	4-8	RS3	4-8
Н	1-2-16	4	1-2-8	RS4	1-2-8
X	2-16	5	2-8	RS5	2-8
Z	16	6	1-8	RS6	1-8
U	4-16	7	8	RS7	1-2-4
W	2-4-16	8	1-2-4	RS8	1-4
I	1-2-4-16	9	2-4	RS9	1-2
K	1-4-16	0	1-2-4-8		
Р	1-4	+	4		
R	4	-	1-4		
F	4-8		1-2		
E	1-4-8				
S	1-2-4-8				
Т	1-2-4				
D	2-4				
M	2-4-8				
L	2-8				
\$/Q	1-2-8				

Code for 1050 MC Keyboard 44B294321-G01

N	1-2-4-8-32	F	1-4-8-16	1	2-4-8	RS1	1-2-4-8
G	2-4-8-32	S	4-8-16	2	1-4-8	RS2	2-4-8
Χ	1-4-8-32	Т	1-2-8-16	3	4-8	RS3	1-4-8
Υ	4-8-32	D	2-8-16	4	1-2-8	RS4	4-8
Ζ	1-2-8-32	E	1-8-16	5	2-8	RS5	1-2-8
R	2-8-32	M	8-16	6	1-8	RS6	2-8
W	1-8-32	U	1-2-32	7	8	RS7	1-8
1	1-2-4-32	1	1-2-4-16	8	1-2-4	RS8	8
J	2-4-32	V	2-32	9	2-4	RS9	1-2-4
K	1-4-32	0	2-4-16	0	1-2-4-8	RS10	2-4
Н	8-32	L	1-2-16	+	4	RS11	1-4
Α	4-32	\$	1-4-16	-	1-4	RS12	4
В	1-2-4-8-16	;	2-16			RS13	1-2
С	2-4-8-16		4-16				

6.2 ***TEST COMPLETE ***

LOU-GEF-1050KYBD
REV. A

GE Energy
Inspection & Repair Services
Louisville, KY

Page 6 of 6

7. REFERENCES

7.1 None at this time