

## PERFORMENTS

## ISOLATED E/I B)

## ASSEMBLY 4145J42

SCHEMATIC 4145J44

- 1. CONNECT PER FIG. 1 S1, S2 OPEN, S3 TO COM
- 2= →E in A(4)/0.00V, R17 (1) → I OUT A(32) = 4.00 +.01MA
- 3. +E IN A(4)/+10.00V, R18 (2) = 0UT A(32) = 20.00 +.01MA TP5 = +9.4 +.6V
- 4. SI CLOSED, I OUT CHANGE LESS THAN . 01MA
- 5. S3 TO -15V, I OUT CHANGE LESS THAN .CIMA
- 6. REPEAT 1 THROUGH 5 FOR B SECTION
- 7. SCOPE ON SYNC OUT (8). SHOULD SHOW 10/12/20 KHZ WITH AMPLITUDE .20 ±3V P-P
- 8. REMOVE +26V FROM PIN 11, S3 TO -15V REMOVE LEADS FROM 32 AND 40
- 9. PUT VOLTMETER TP6 TO COM AND APPLY +15V TO +1 OUT A(32) FOR A FEW SECONDS ONLY. TP6 = +7.5 +1V
- 10. REPEAT 8 FOR B SECTION USING  $\diamond$ I OUT B(40) AND TP4

PERFORMANCE REQUIREMENTS ISOLATED E/F BD

SIGNATURES DAY NO YE A 012 R9

SH 2

GE-102

