		~		68 4 9 9 3	3 1 9		1
REY HO, Å	TITLE			CONT ON SHEET FL	SH NO.	1	/
684993319	1	NT SENSOR AMPLIFIE SPECIFICATIONS	₹			*	
CONT ON SHEET FL. SH. NO. 1	FIRST MADE FO	OR 1 C3 600A 1AA B	r-r				
6	THO MADE I	311 · (COLDON 171 · 151	<u> </u>			REVISI	1082
ELEMENTARY	1C3600A IAA	1C3600A1A6	3, iC3600A1AC	IC36XXX IAEI	Į 4	α	7:5
POWER INPUT		N 50, COMMON ON PI			. 10	3/2	-
P		PEAK TO PEAK SQUARI A OR AVIB PIN 30 AI				- I	
CHECK FLOATING POWER			O SEI Grap	VIC or bac)	8	
VOLTAGE FROM PIN 30		8 SHOULD BE 22 ≠2 V	OLTS: VOLTAGE	F30M PIN 26 /-	-) ²	1 =	[در
TO PIN 28 SHOULD 22			ociat todinac	1.1001 1.10 20 1.	ā	Ψ.	
ZERO AMPLIFIER			•		٦	(22	-',
SHORT INPUT PIN (16)	TO PIN (18)				ដ	4	C]
R50 CV ADJUST R51 FOR ZERO C	OATJEV -YUSTUK	E' ± 5 MV FROH PIN-	12 TO PIN 14.				\prod
R50 CCW ADJUST R51 FOR ZERO (YER IFY PIN 24 TO FCOM # CHECK GAIN KANGE	олгрит-үөLTAG 4 (28) is 2.7	E I S MY FROM PIK	12 TO PIR 14.			69/)
APPLY A 50 MV DC SI	GWL TO PINS	(16) AND+ (16), AD	JUST R50 FRCM	CCW TO CW. OUT	ניטז 🦉	2 2	3
VOLTAGE SHOULD VARY	AS FOLLOWS.	A LAA AND A LAB. 2	TO 15± 1V V	DLTS.AIACT 4.4	. 2	9 0	14.5
. Sv TO 12.5Sv.	. LEAVE R50 II	N MAXIMUM. CW. POS IT	10N.			NNAH	パン
CHECK SATURATION LE	VEL .		•		78	of 1.	, K
CONNECT 2,2K LOAD F		PIN 1A LPPIVA	מוני שני חר פור	SEE TA DINC LA	. 1865 121	23.	(`
OUTPUT MUST BE AT L					ř	र र	1
		s. seresa, neo,	STGIME, OUTFO	I WAST DE YI F	5731	5.	
20V WITH OPPOSITE P GAIN LINEARITY	OLAKIII.	•		•		74	7.1
(A) ADJUST GAIN POT			•			3	9-7
(01 APPLY JUMPER BE (c) ADJUST HULL POT 16 TO 18.			PINS 6 AND 8.	REMOVE JUMPER	PINS }	WRIGHT	75 K
(D) APPLY POSITIVE I			ND ADJUST FOR	OUTPUT OF +15	.00 %	3 3	Ų
VOLTS [±] 10HV AT : (E) REVERSE POLARIT			THAT YALUE OF	OUTPUT IS -15	.00	4 6	×
VOLTS ±50HV FR	CM PIN 12 TO	PINTA.			3	4.5	¥ €
TRIMPOT SUPPORT	_	· & .	•		-		1
ASSURE THAT BEAD OF		RETHANE HAS BEEN AF	PLIED TO BUSE	OF TRIMPOT			
FOR MECHANICAL SUPP					8	DL1	19
APPLY A 100MW DC SI		-			TYPING		
ADJUST REO FROM COW			ARY AS FOLLOW	s: _≃	5 5	1	
14VOLTS TG 22 45 VOL	.TS. LEAVE REC) IR HAXIHUH CV POS	SITION.	6/29//8 PJR 809384FH BU945GK	784/		
				6/29//8 60938AFW BUS45GR	2 2		
				6/29//8 6/29//8 809384Fh 80945GR	કે કિ		\neg
				70 4	n 2	PRINTS	s To
	APPROVALS	ORIVE SVETOVE	גס יחם	1-1-			
J. H. SMITH	STC.	DRIVE SYSTOMS	иг	-	3:9	<u></u>	

