g		GE Energy	Functi	onal Testing Sp	ecification	
Parts & Repair Operations Louisville, KY				LOU-GEF-IC600RM715		
Test Procedure for a Series Six RPU Memory card (IC600RM715).						
DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column						
REV.		DESCRIPTION		SIGNATURE	REV. DATE	
Α	Initial release			Cristyn Edlin	5/28/10	
В						
С						
© COPYRIGHT GENERAL ELECTRIC COMPANY Hard copies are uncontrolled and are for reference only. PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.						
Cristy	n Edlin	REVIEWED BY	REVIEWED BY	QUALITY AP Charlie Wa		
<b>DATE</b> 5/28/1	0	DATE	DATE	<b>DATE</b> 6/2/2010		

LOU-GEF-IC600RM715
REV. A

GE Energy
Parts & Repair Operations
Louisville, KY

Page 2 of 3

#### 1. SCOPE

1.1 This is a functional testing procedure for a Series Six RPU Memory card (IC600RM715).

### 2. STANDARDS OF QUALITY

**2.1** Refer to the current revision of the IPC-A-610 standard for workmanship standards.

#### 3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
  - **3.1.1** Check board's electronic folder for more information

## 4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
  - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.
- **4.2** Equipment Inspection
  - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
    - 4.2.1.1 Wires: broken, cracked, or loosely connected
    - **4.2.1.2** Terminal strips / connectors: broken or cracked
    - 4.2.1.3 Components: visually damaged
    - 4.2.1.4 Capacitors: bloated or leaking
    - 4.2.1.5 Solder joints: damaged or cold
    - 4.2.1.6 Circuit board: burned or de-laminated
    - 4.2.1.7 Printed wire runs / Traces: burned or damaged

### 5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1	H188896	RPU-1 Main
1	H188889	CPU Workmaster

GE Energy
Parts & Repair Operations
Louisville, KY

## LOU-GEF-IC600RM715 REV. A

#### 6. TESTING

### 6.1 Setup

- **6.1.1** Remove the top cover-shield to verify that all RAM chips are properly seated in the card and to check the batter voltage.
- **6.1.2** Verify that all RAM chips are seated properly in their sockets.
- **6.1.3** Ensure that the battery voltage is no less than 3.2VDC.
- **6.1.4** Ensure that the jumper and dipswitch settings are set in accordance with GEK-84873.
- **6.1.5** Turn off power to RPU-1 Main.
- **6.1.6** Remove the shop card from slot 3 of RPU-1 Main.
- **6.1.7** Install the customer card into slot 3 of RPU-1 Main.

## 6.2 Test Process

- **6.2.1** Turn on power to RPU-1 Main.
- **6.2.2** Ensure that the battery indicator LED lights.
- **6.2.3** Ensure that that the Device Switch card (located in slot 8) displays a "1" on its digital readout.
- **6.2.4** Ensure that the Device Switch will toggle between CPU-1 and CPU-2 when selecting CPU-1 or CPU-2 from the "Auto" key switch (located on RPU-1 Main's power supply).
- **6.2.5** Turn off power to RPU-1 Main.
- **6.2.6** Remove the customer card from slot 3 of RPU-1 Main.
- **6.2.7** Install the shop card into slot 3 of RPU-1 Main.
- **6.2.8** Test complete.

## 7. NOTES

**7.1** None at this time.

# 8. ATTACHMENTS

**8.1** None at this time.