ASSEMBLY DRAWING

PC BOARD DRAWING

878E576G1

4053J24-D

SCHEMATIC DRAWING

TEST KIT

UNIVERSAL TEST KIT

1.0	INSPECTION			
	.l Identification	.3 Solder/Wire	.5 Key Slot	
	.2 Comp./Conn.	.4 Temp. Cycle	.6	
			.7	
REMARKS: MA METER AT PIN 11 HAS AN INTERNAL RESISTANCE OF 3.5 OHMS.				
2.0 <u>PRI</u>	EPARATION			
2.1 CONNECT +30 VDC TO PIN 17, -22 VDC TO PIN 21, +26 VDC TO PIN 28 AND POWER COMMON TO PIN 19.  2.2 CONNECT (-) TERMINAL OF 10 MA METER TO PIN 11.  2.3 CONNECT LAMP FROM PIN 27 TO COMMON.  2.4 CONNECT VARIABLE 5 VDC VOLTAGE SOURCE TO PIN 24.  2.5 PLUG P.C. BOARD INTO TEST KIT.  2.6 SET R54 FULL CCW.				
3.0 METER ZERO				
3.1 S 3.2 A	SET VOLTAGE AT PIN 24 (TP5) F ADJUST (1) R33 TO READ O AT P	OR +1.0 VDC. IN 11 METER.		
4.0 METER GAIN				ı
	SET VOLTAGE AT PIN 24 (TP5) FOLDJUST (2) R36 TO READ 10 MA		,·	
5.0 TRIGGER SETPOINT				
5.2 L 5.3 S	ET VOLTAGE AT PIN 24 (TP5) FO AMP AT PIN 27 SHOULD BE ON. ET VOLTAGE AT PIN 24 (TP5) FO DJUST 3 R54 SO THAT LAMP AT	OR +5.0 VDC.		