

OFFICE OF THE VICE PROVOST FOR RESEARCH

Industrial Hygiene Group | Tufts University

Hazard Assessment Form

| General information | | |
|---|---------------------------------------|--|
| Department ECE | Supervisor Paul Simmonds | Work site 200 Boston Ave |
| Brief description of job task: Maintainece of molecular beam epitaxial machinery | | |
| Job classification: | | |
| Level of physical exertion required to perform the job: | | |
| Light (less than 200 kcal per hour): | Moderate (200 to 350 kcal per hour) | Heavy (above 350 kcal per hour) |
| Hazards | | |
| Type of hazard | Biological | Chemical Radiation |
| Enumerate and describe: Particulates from inside the chaber include arsenic atoms | | |
| Chemical hazards | Name | |
| Regulatory limits | OSHA PEL | ACGIH TLV |
| Monitoring data | | |
| Contaminant concentration | Is this above the OSHA PEL? Yes/No | Is this at IDLH concentration? Yes/No |
| Is the work being done in an | Yes | No |
| O ₂ deficient atmosphere? | | |
| Controls | | |
| Are engineering controls used? | Yes | No |
| Describe | | |
| Is a respirator used for routine tasks | Yes | No |
| Type of respirator selected | Air Purifying | Atmosphere supplying |
| Style of respirator | Tight fitting | Loose fitting |
| Additional comments: | | |
| Name of the person that completed the Assessment and role: | | |
| Date: | | |