Date 10/02/26 Loco No. RL005 Cab No 1 Facing Andoom Shift Driver/s NEV GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓50	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 Y N Rake 3 (Y) N	Rake 1 (0) Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added / Comp Car Amt Added	Comp Car Amt Added / Comp Car Amt Added	Comp Car Amt Added / Comp Car Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added
Rake 3		Comp Hrs				Loco Hrs 22771
		Next Service				Cab Cleaned COVID
Locomotive	1630		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 466141
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	2603 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1549		1626	1642	NO		1		
2	1717		1757	1820	NO		2	M/C	
3	1855		1932	2004	NO		3	"	
4	2039		2114	2149	NO		1	"	
5	2224		2314	2349	NO		2		
6	0025		0058	0151	NO		3		
7	0224		0309	0350	NO			Fuel loco	
8	0423								
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.