Date 11 / 06 / 2026 Loco No. RI007 Cab No 2 Facing Andoom Shift Driver/s NEV / ADAM (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 Rake 3
Loco Comp Oil ?	(OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0740	Engine Oil	Comp Car J		Comp Car O	Comp Car P		Comp Car K	Comp Car M		Comp Car 1	Radiator Water added(mm s/glass)
Rake 2	0345	Comp Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3	0545	Comp Hrs	16311		33149	16499		8137	18141		10985	Loco Hrs
		Next Service	16500		33500	17057		9100	19000		11000	Cab Cleaned COVID
Locomotive	0425		(Running in Auto / Manual) Not Running		Running in Auto / Manual (Not Running)	(Running in Auto / Manual) Not Running		Running in Auto / Manual (Not Running)	(Running in Auto / Manual) Not Running		Running in Auto / Manual (Not Running)	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's		Ltr's	Ltr's		Ltr's	225 Ltr's		Ltr's	3400 800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0412		0511	0534	N		2	fuel loco	
2	0615		0657	0706	N		3	M/C R3	
3	0737		0829	0843	N		1	R1	
4	0920		0957	1030			2	SWAP Locos, Loco Down R2	
5	1150		1235	1306	N		3		
6	1341		1412	1436	N		1		
7	1511						2		
8							3		
9							1		
10							2		
11							3		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0930	Loco 5 in Production		
	Comp's ALL changed over, fueled + oils Topped up		
1511	Rake Mover stuffed 12 to Dump		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 11, 6, 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s GARY - TRUDI Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	Ok Not OK Topped up L100	(OK) Not Ok Topped Up		Rake 1 Y N Rake 2 (Y) N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs 24817
	Next Service									Cab Cleaned COVID
Locomotive 1630	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 499568
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1511	1550	1620	1630	Yes	30 reduced	2	Compressor Issues @ Dump Station	
2	1703		1535	1800	NO		3		GM
3	1933		1904	1929	NO		1		GM
4	2002		2038	2101	NO		2		GM
5	2134		2207	2234	NO		3		
6	2308						1	2315: POWER OUT LP + ANDOOM	
7								0322: fuel loco	
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....