Date 26/03/26 Loco No. RIOO5 Cab No 2 Facing Andoom Shift Driver/s JED Steve Pete Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Amt Added
		Next Service										Loco Hrs
Locomotive			Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled
												Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1			1755	1755	No		2		
2	1830		0116	0249	N		3		
3	0324						1		
4									
5									
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....