Date 26.6.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Pete / Steve Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	OK Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken		Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Comp Car Amt Added / Comp Car Amt Added	Comp Car Amt Added / Comp Car Amt Added	Comp Car Amt Added / Comp Car Amt Added	Radiator Water added(mm e/pless)
Rake 2		Engine Oil: Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3		Comp Oil: Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
		Comp Hrs			Loco Hrs
		Next Service			Cab Cleaned covid
Locomotive		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco		Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1602		1647	1651			1		PH
2	1725		1819	1822			2		PH
3	1855		1933	1942			3		PH
4	2017		2053	2103			1		
5	2138		2214	2226			2		
6	2300		2330	2352			3		
7	0027						1	Dump: delays - stacker	
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R1 manual load		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....