GLEN

Date 26/9/26 Loco No. IC1007 Cab No 2 Facing Andoom Shift Drivers [redacted] Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd

Record time comp car/loco hrs taken		Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Locomotive
Rake 1		Engine Oil Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs						Loco Hrs 7684
		Next Service						Cab Cleaned (COVID)
Locomotive		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 538989
Fuel added to comp cars // Loco		Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	4200 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1615		1655	1657			2		MC SM
2	1732		1805	1820			3		MC SM
3	1855	1900	1930	1940			1	Stacker Move.	MC SM
4	2015	2100	2130	2132			2	Meal Break. 2030-2100	SM
5	2207		2235	2257			3		
6	2332		0005	0015			1		
7	0050		0120	0136			2		
8	0211						3	Fuelled Loco 4200 Ltrs.	
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....