Date 27/8/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Glen-Rob Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N / Rake 2 Y N / Rake 3 Y N	Rake 1 / Rake 2 0 / Rake 3
Loco Comp Oil	OK / Not OK / Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car P	Comp Car T		Comp Car O	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0545	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0410	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0545	Comp Hrs	17258	11472		33625	8552		16884	18738		Loco Hrs 7419
		Next Service	18137	12000		34500	9100		17500	19000		Cab Cleaned COVID
Locomotive	0425		~~Running In Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~		Running In Auto / ~~Manual~~ Not Running	~~Running In Auto / Manual~~ Not Running		Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		Loco Km's Travelled 524775
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0416	0425	0450	0510			2	ML	
2	0545						3		
3							1	MC	RR
4							2		
5							3		
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 27.8.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 ( ) Rake 2 ( ) Rake 3 ( )

Loco Comp Oil ? (OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car O	Comp Car		Comp Car J	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs
	Next Service									Cab Cleaned COVID
Locomotive 0124	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 524913.1
Fuel added to comp cars / Loco	Ltr's	Ltr's		62 Ltr's	Ltr's		52 Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0545	2127	2207	2207	Y		3	Massive Delay Dump	
2	2242		2321	0003	N		1		
3	0836		0123	0131	N		2		
4	0206		0243	0257	N		3		
5	0332						1		
6							2		
7							3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....