Date 27.06.2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil ?	OK Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car O		Comp Car P	Comp Car K		Comp Car N	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0636	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0847	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0535	16450	33273		16695	8209		35766	18231		Loco Hrs
	16500	33500		17057	9100		36052	19000		Cab Cleaned COVID
Locomotive 0748	Running In Auto / Manual (Not Running)	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual (Not Running)		Running In Auto / Manual (Not Running)	Running In Auto / Manual Not Running		Loco Km's Travelled 505858.8
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2000+3200 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0027		0454	0454	Y		2	Dump delays - stacker	R + SW
2	0528		0626	0635	N		3	fuel loco	R + SW
3	0709		0748	0800	N		1		R + AR
4	0834		0925	0927	N		2		
5	1001		1050	1054	N		3	Manual load required	
6	1128		1238	1238			1	20 M crew break 1140 - 1200	
7	1312		1405	1405			2	Stop inspect R2	
8	1445						3	fuel loco	
9									
10								600L in R1005	
11								R1007 5200L fuel	
12									

(load light came on but 2nd CC in transit)

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R1 Manual load at shift start		
	R3 needed manual load + manual dump. Change to Nonce dumped - DONE		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....