Date 27/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s TRUDI GARY Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Ø Rake 2 Ø Rake 3 Ø
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
			Comp Car I / Comp Car N	Comp Car P / Comp Car K	Comp Car J / Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0543	Engine Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 2	0701	Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3	0425	Comp Hrs	11315 / 35954	17054 / 8339	16678 / 18446	Loco Hrs 25405
		Next Service	12000 / 36800	17057 / 9100	17500 / 19000	Cab Cleaned COVID
Locomotive	0615		Running in Auto / Manual Not Running (Not Running) / Running in Auto / Manual Not Running (Not Running)	Running in Auto / Manual Not Running (Running in Auto / Manual Not Running) / Running in Auto / Manual Not Running (Not Running)	Running in Auto / Manual Not Running (Running in Auto / Manual Not Running) / Running in Auto / Manual Not Running (Not Running)	Loco Km's Travelled 513805
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	2000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0426		0502	0511	NO		3	R3 sticky brakes. ~~Gmore~~ x2	
2	0545		0615	0630	NO		1		
3	0705		0732	0754	NO		2		
4	0828		0910	0922	NO		3	fuel loco 2000L	
5	0956		1027	1045	NO		1		
6	1118		1148	1210	NO		2		
7	1243		1311	1336	NO		3		
8	1409	1438	1507	1509	NO			Dump not Detected	
9	1542								
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....