Date 8/7/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Gary - TRUP Day (Night) Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (Ok) Not OK Topped up | (Ok) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 Rake 2 0 Rake 3 0 |
| Loco Comp Oil | OK Not OK Topped Up | | | |

| Record time comp car/loco hrs taken | | | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Rake 1 | | Engine Oil | Comp Car Amt Added | Comp Car Amt Added | | Comp Car Amt Added | Comp Car Amt Added | | Comp Car Amt Added | Comp Car Amt Added | | Radiator Water added(mm s/glass) |
| Rake 2 | | Comp Oil | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 | | Comp Hrs | | | | | | | | | | Amt Added |
| | | Next Service | | | | | | | | | | Loco Hrs |
| Locomotive | 1545 | | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running in Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Cab Cleaned COVID |
| Fuel added to comp cars / Loco | | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | Loco Km's Travelled 511078 |
| | | | | | | | | | | | | 2200 Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 1535 | | 1607 | 1737 | NO | | 2 | Andoom power out | |
| 2 | 1810 | | 1840 | 1856 | NO | | 3 | | |
| 3 | 1930 | | 2002 | 2013 | NO | | 1 | | |
| 4 | 2046 | 2053 | 2123 | 2133 | NO | | 2 | | |
| 5 | 2206 | | 2239 | 2253 | NO | | 3 | | |
| 6 | 2327 | | 0000 | 0015 | NO | | 1 | | |
| 7 | 0049 | | 0120 | 0140 | NO | | 2 | | |
| 8 | 0214 | | 0300 | 0308 | NO | | 3 | | |
| 9 | 0342 | | | | | | 1 | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*