Date 8/8/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s GLEN – ROB (Day) Night Shift

The following checks are to be performed at shift handover or as close as practical

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (OK) Not OK Topped up | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 0 Rake 2 0 Rake 3 0 |

| Loco Comp Oil | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|
| (OK) Not OK Topped Up | Comp Car I | Comp Car N | | Comp Car O | Comp Car K | | Comp Car J | Comp Car M | | Radiator Water added(mm e/glass) |

| Record time comp car/loco hrs taken | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Rake 1 | 0350 | Engine Oil | Amt Added | | Amt Added | | Amt Added | | Amt Added | | Amt Added | |
| Rake 2 | 0510 | Comp Oil | Amt Added | | Amt Added | | Amt Added | | Amt Added | | Amt Added | |
| Rake 3 | 0635 | Comp Hrs | 11425 | | 36031 | | 33498 | 8371 | 16753 | 18520 | Loco Hrs | 7319 |
| | | Next Service | 12000 | | 36800 | | 34500 | 9100 | 17500 | 19000 | Cab Cleaned COVID | |
| Locomotive | 0400 | | ~~Running In Auto / Manual~~ Not Running | | Running In Auto / ~~Manual~~ ~~Not Running~~ | | ~~Running In Auto / Manual~~ Not Running | Running In Auto / ~~Manual~~ ~~Not Running~~ | Running In Auto / ~~Manual~~ ~~Not Running~~ | ~~Running In Auto / Manual~~ Not Running | Loco Km's Travelled | 519433 |
| Fuel added to comp cars / Loco | | | Ltr's | | Ltr's | | Ltr's | | Ltr's | | 4000 | Litre |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0350 | | 0405 | 0445 | | | 1 | | |
| 2 | 0520 | | 0552 | 0603 | | | 2 | | MC DM RR |
| 3 | 0636 | | 0710 | 0731 | | | 3 | | MC DM RR |
| 4 | 0806 | | 0840 | 0901 | | | 1 | Fuelled Loco 1000 Ltrs | MC DM RR |
| 5 | 0936 | | 1010 | 1025 | | | 2 | | |
| 6 | 1100 | | 1139 | 1148 | | | 3 | " " 1050 L | |
| 7 | 1224 | 1232 | 1303 | 1313 | | | 1 | AF 7 checks | |
| 8 | 1343 | 1416 | 1448 | 1452 | | | 2 | Fuel loco 2000L/Stacker Fault LP | |
| 9 | 1528 | | | | | | 3 | Stacker Fault LP | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*