Date 8/8/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s Nev / Adam Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 / Rake 2 / Rake 3

Loco Comp Oil 7	OK Not OK Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken		Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm e/glass)
Rake 1		Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2		Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs									Loco Hrs
		Next Service									Cab Cleaned (cover)
Locomotive		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1528		1614	1635	NO		3	MC R3	PR
2	1710		1753	1802	NO		1	NO Com's with Control R1	
3	1837	2002	2046	2209	N		2	fuel Loco 700 R2	
4	2244		2323	2333	N		3		
5	0008	0204	0247	0247	Y		1	COMMS ISSUE	
6	0322						2		
7							3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
1815	Lost Comms with Brisbane		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....