Date 8/9/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s Steve/Ted/Pete Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
Yes / No	OK / Not OK / Topped up	OK / Not Ok / Topped Up		Rake 1 Y N	Rake 2 Y N	Rake 3 Y N	Rake 1	Rake 2	Rake 3
Loco Comp Oil	OK / Not OK / Topped Up								

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3			Comp Hrs							Loco Hrs
			Next Service							Cab Cleaned COVID
Locomotive	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1500 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1636		1709	1729	N		3		SPW
2	1804		1838	1908	N		1		SPW
3	1943		2015	2037	N		2		SPW
4	2112		2142	2208	N		3		
5	2243		2327	2348	N		1		
6	0023		0102	0118	N		2		
7	0153		0243	0249	N		3		
8	0325						1		
9							2		
10							3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....