Date 9/3/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Drivers ADAM / ~~TROY~~ Day Night Shift

Vigilance Operational: Yes / No — Loco Comp Oil: OK / Not OK / Topped Up — Engine Oil: Ok / Not OK / Topped up — Radiator Water: OK / Not Ok / Topped Up

The following checks are to be performed at shift handover or close as practical

End of Rake Marker Operational: Rake 1 Y / N — Rake 2 Y / N — Rake 3 Y / N

Rake Leakage Check kPa: Rake 1 0 — Rake 2 0 — Rake 3 0

Record time comp car/loco hrs taken	
Rake 1	0409
Rake 2	0830
Rake 3	0412
Locomotive	0457

Fuel added to comp cars / Loco:

	Lead Rake1	2nd	Lead Rake2	2nd	Lead Rake3	2nd	Locomotive
	Comp Car J	Comp Car K	Comp Car P	Comp Car N	Comp Car L	Comp Car M	
Engine Oil Amt Added							Radiator Water added(mm s/glass)
Comp Oil Amt Added							Amt Added
Comp Hrs	15850	7541	15926	35128	10401	17546	Amt Added
Next Service	16500	8100	16000	36200	11000	18137	Loco Hrs
	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Cab Cleaned (COVID)
	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Loco Km's Travelled 475199
							1800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0405		0450	0526	N		3		
2	0601		0640	0715	N		1	m/c	PH
3	0750		0830	0932	N		2	m/c	PH
4	1007		1047	1145	N		3		
5	1220		1300	1350	N		1		
6	1425						2	FUEL 1800L, windspeed 70km	
7							3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....