Date 16/08/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Steve H Jed Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up ↓ 110	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken		Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1	Engine Oil	Comp Car ___ Amt Added	Comp Car ___ Amt Added	Comp Car ___ Amt Added	Radiator Water added(mm s/glass)
Rake 2	Comp Oil	Comp Car ___ Amt Added	Comp Car ___ Amt Added	Comp Car ___ Amt Added	Amt Added
Rake 3	Comp Hrs	Comp Car ___ Amt Added	Comp Car ___ Amt Added	Comp Car ___ Amt Added	Amt Added
	Next Service				Loco Hrs
Locomotive		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco		Ltr's	Ltr's	Ltr's	Loco Km's Travelled
					Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1610		1640	1707			N		
2	1742		1812	1847			N		
3	1917		1947	2015			N		SSM SR
4	2050		2215	2257			N		SSM SR
5	2332		0004	0033	No		1		SSM SR
6	0108		0138	0206	No		2		
7	0241		0311	0403	No		3		
8	0438						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....