Date 17.3.26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s STEVE - JED - PETE (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓70	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N / Rake 2 Y N / Rake 3 Y N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0645	Engine Oil	Comp Car 5	Comp Car K		Comp Car P	Comp Car N		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2	0530	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service	15722	7599		16007	35174					Loco Hrs
Locomotive			16500	8100		16000	36000					Cab Cleaned COVID
			(Running in Auto / Manual) Not Running	Running in Auto / Manual (Not Running)		(Running in Auto / Manual) Not Running	Running in Auto / Manual (Not Running)		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0302		0400	0445	No		3		[redacted]
2	0520		0600	0713	No		1		BPM
3	0748		0836	0930	No		2		S.PM
4	1005.		1043	1240	No		3		S.PM.
5	1310		1346	1455	No		1		
6	1530						2		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....