Date 2/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Molly-Gary Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	OK Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0500	Engine Oil	Comp Car J	Comp Car O		Comp Car P	Comp Car R		Comp Car 1	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0645	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0330	Comp Hrs	Amt Added 16283	Amt Added 33035		Amt Added 16490	Amt Added 8059		Amt Added 10952	Amt Added 18031		Amt Added Loco Hrs 24617
		Next Service	16500	33500		17057	9100		11000	19000		Cab Cleaned COVID
Locomotive	0400		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 495011
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0320		0407		NO		3	MC	MC
2	0455		0539		NO		1	MC	M.M. MC
3	0640		0730		NO		2	MC	M.M. MC
4	0820		0850		NO		3		
5	0955		1028	1053	NO		1		
6	1125		1158	1229	NO				
7	1302		1325	1359					
8	1432								
9								Fuel 2500L	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 2/6/26 Loco No. P1005 Cab No 2 Facing Andoom Shift Driver/s Adam/Wes Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	60 Ok / Not OK / Topped up	50 OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 2 Rake 2 0 Rake 3 0
Loco Comp Oil: OK / Not OK / Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Radiator Water added(mm s/glass)
Rake 1	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 2	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3										Loco Hrs
										Cab Cleaned COVID
Locomotive 1623	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Loco Km's Travelled 495129
Fuel added to comp cars / Loco	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1437		1610	1655	N		1		
2	1730		1810	1825	N		2		
3	1900		1940	1954	N		3		
4	2029		2106	2128	N		1		
5	2203		2237	2302	N		2		
6	2337		0015	0034	N		3		
7	0109		0140	0212	N		1		
8	0243		0331	0348	N		2	fuel Loco	
9	0423						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....