Date 21/7/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Glen - Rob (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up Needs top up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 ( ) Rake 2 ( ) Rake 3 ( )
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car +		Comp Car O	Comp Car P		Comp Car K	Comp Car W		Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0825	Engine Oil	Amt Added		Amt Added 2½ 4Rs	Amt Added 1 4R		Amt Added	Amt Added		Amt Added 1½ 4R	Amt Added
Rake 2	0435	Comp Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3	0605	Comp Hrs	11139		33356	16775		8209	35809		18268	Loco Hrs 7120
		Next Service	12000		33500	17057		9100.	36025		19000	Cab Cleaned COVID ✓
Locomotive	0325		Running in Auto / ~~Manual~~ ~~Not Running~~ Not Running		~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 508239
Fuel added to comp cars / Loco			80. Ltr's		178 Ltr's	226. Ltr's		Ltr's	109 Ltr's		139 Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0245		0350	0403			1		
2	0441.	0455	0520	0535			2	Comp K Wouldn't start Comp P ok	MC RR
3	0610	0625	0655	0705			3		MC RR
4	0740	0845	0915	0915			1		MC RR
5	0950	0953	1023	1039			2		
6	1115	1136	1207	1207			3	Rake mover 1 problems.	
7	1243	1302	1332	1333			1		
8	1409	1448	1519	1521			2		
9	1557						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 2.7.26 Loco No. 5 Cab No Facing Andoom Shift Driver/s Adam Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	OK / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK / Not OK / Topped Up			

Record time comp car/loco hrs taken		Engine Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Comp Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Next Service										Loco Hrs
Locomotive	2091		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Cab Cleaned COVID
Fuel ladder/ comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled 505546
												2800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1557		1637	1640	N		3	MC A3	RD
2	1715		1749	1754	N		1	MC A1	RR
3	1829		1919	1923	N		2		
4	1954		2039	2041	N		3		
5	2116		2152	2157	N		1		
6	2232		2308	2314	N		2		
7	2349		0037	0037	N		3	~~Comp car~~ M Didnt start	
8	0112		0151	0157	N		1		
9	0232						2	2800L Fuel	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	RAKE 3 Manual Dump comp car M no start		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....