Date 2.10.26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Adam Alex Day / Night Shift

The following checks are to be performed at shift hand over or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil: OK / Not OK / Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3										Loco Hrs
Next Service										Cab Cleaned COVID
Locomotive 2018	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 528814
Fuel Ltr's prior comp / loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2200 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1520		1559	1606	N		3		AK
2	1641		1702	1728	N		1		
3	1803		1840	1936	N		2	Delay Andoom	
4	2011		2047	2059	N		3		
5	2134		2209	2215	N		1		
6	2250		2322	2344	N		2		
7	0020		0052	0103	N		3		
8	0138		0218	0224	N		1	fuel loco 1200	
9	0300		0343	0400	N		2	" " 1000	
10	0435						3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....