Date 24 / 1 / 26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Glen (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 1

Loco Comp Oil: (OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car N		Comp Car T	Comp Car P		Comp Car O	Comp Car K		Comp Car M	Radiator Water added(mm s/glass)
Rake 1 0545.	Engine Oil Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 2 1510.	Comp Oil Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3 1005.	Comp Hrs 34967		15433	15346		32753	7156		17254	Loco Hrs 22350
	Next Service 35000		15500	16000		33500	7001		18137.	Cab Cleaned COVID
Locomotive 0322.	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	Running in Auto / ~~Manual~~ ~~Not Running~~		~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 457924.
Fuel added to comp cars / Loco	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0300	0322	0350	0458			3		
2	0533		0615	0720			1		
3	0755		0830	0927			2		MC CW
4	1002	1045	1115	1210			3	Replaced Hoseson Comp "K"	MC CW
5	1245		1320	1432			1		MC CW
6	1507						2		
7							3		
8							1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 24/12/26 Loco No. R1055 Cab No 1 Facing Andoom Shift Driver/s New GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1	2nd	Lead Rake2	2nd	Lead Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass) / Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 22362
		Next Service							Cab Cleaned COVID
Locomotive	1550		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 458138
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2400 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1507		1547	1650	N		2	–	
2	1725		1820	1910	N		3	fuel Loco	
3	1945		2019	2125	N		1		
4	2200		2331	2343	NO		2		
5	0016		0049	0206	NO		3	Red over White 21 switch	
6	0234		0311	0510	NO				
7	0543								
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....