Date 24/01/26 Loco No. RL1005 Cab No 2 Facing Andoom Shift Driver/s Pete/Steve/Jed (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	(OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car P		Comp Car M	Comp Car O		Comp Car K	Comp Car I		Comp Car L	Radiator Water added(mm s/gless)
Rake 1 0920	Engine Oil Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 2 0627	Comp Oil Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3 0835	Comp Hrs 17662		19076	34109		8917	11819		143	Loco Hrs 26493
	Next Service 18137		20000	34500		9100	12000		1001	Cab Cleaned COVID
Locomotive 0405	Running in Auto / ~~Manual~~ ~~Not Running~~		~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 537350
Fuel added to comp cars / Loco	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0250		0415	0415	N		3		
2	0450		0524	0554	N		1		
3	0630		0711	0723	N		2	m/c	PH SE
4	0758		0829	0842	N		3	m/c	PH SE
5	0917		0951	1006	N		1	LOCO FUEL 1500L m/c	PH SE
6	1041			1137	Yes	14 Full	2	E/W Roller change.	
7	1212	1222	1259	1352	No		3		
8	1427		1456	1513	No		1		
9	1548						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 24/10/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Rob Glen Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service										Loco Hrs 26504
Locomotive	1555											Cab Cleaned COVID
			Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 537644
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1500 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1548		1620	1633			2	MC R2	RR SW
2	1709		1741	1758			3	MC R3	RR GM
3	1834		1906	1920			1	MC R1	RR GM
4	1956		2026	2045			2		
5	2121		2151	2224			3	Fuel loco 1500L	
6	2300		2330	2350			1		
7	0025		0055	0120			2		
8	0155		0225	0241			3		
9	0316		0345	0413			1		
10	0446						2		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....