Date 24/4/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Nev / Adam Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓90	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car J	Comp Car K		Comp Car P	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0900	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0450	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0650	Comp Hrs	15921	7921		16148	35505		10688	17898		Loco Hrs 24063
		Next Service	16500	8100		17057	36052		11000	18137		Cab Cleaned COVID
Locomotive	0350		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 486264
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1300 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0240	0348	0416	0420			1		
2	0455		0534	0640	N		2	M/C	
3	0715		0752	0854	N		3	M/C	
4	0930		1020	1105	N		1	M/C	
5	1140		1243	1315	N		2	Compressor worked on N now Running	
6	1350		1450	1535			3	1300 L Fuel added	
7	1000						1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Compressor N now running Rake 2 as per workshops		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....