Date 24 / 05 / 2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s NEV ADAM MOLLY (Day) Night Shift

The following checks are to be performed at shift handover/or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	10W (Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs
	Next Service									Cab Cleaned (COVID)
Locomotive 1024	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 50378.2
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1235								
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Yellow Dipstick below Add		

A Continuity Test must be done before moving the Train after Rake changeover!

Document revlewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....